

Reilley - DNR, Robin <robin.reilley@state.co.us>

Inspection WF 2024 March

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us> Thu, Mar 7, 2024 at 7:54 AM To: "Kawcak, Miranda" <MKawcak@peabodyenergy.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Morning Miranda

Please find the March 2024 inspection report for the Williams Fork Mine. This was a partial inspection.

Please let me know of any questions you may have.

Thank you

Robin Reilley, M.S. GISP **Environmental Protection Specialist II**



Division of Reclamation, Mining and Safety Department of Natural Resources

P 303.866.3567 ext 8105 F 303.832.8106 Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203 Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216 robin.reilley@state.co.us | http://mining.state.co.us

INSP_Partial_WF_2024_03March.pdf 440K



PERMIT INFORMATION

Permit Number: C-1981-044 **Mine Name:** Williams Fork Mines **Operator:** Moffat County Mining, LLC

Operator Address: Ms. Miranda Kawcak 29515 Routt County Road #27 Oak Creek, CO 80467 County: Moffat Operation Type: Underground Permit Status: Active Ownership: Private

Operator Representative Present:

None as the site is inaccessible

Operator Representative Signature: (Field Issuance Only)

This report was issued electronically from the Divisions' Denver Office.

INSPECTION INFORMATION

Inspection Start Date: 5 March 2024 Inspection Start Time: 11:30 a.m. Inspection End Date: 6 March 2024 Inspection End Time: 8:30 a.m.			Inspection Type: Partial Inspection Inspection Reason: Normal I&E Weather: Cloudy	
Joint Inspection Agency:		Joint Inspection Contacts:		
None				
Post Inspection Agency:		Post Inspection Contacts:		
None				
Inspector(s):	Inspector's Sign		nature: Signature Date:	
Robin Reilley, M.S. GISP	Bobin &		eilley	
			7 March 2024	

Inspection Topic Summary NOTE: Y=Inspected NA=Not Applicable	N=Not Inspected R=Comments Noted V=Violation Issued		
Y - Air Resource Protection	R - Roads		
N - Availability of Records	N - Reclamation Success		
N - Backfill & Grading	N - Revegetation		
N - Excess Spoil and Dev. Waste	N - Subsidence		
N - Explosives	N - Slides and Other Damage		
N - Fish & Wildlife	N - Support Facilities On-site		
N - Hydrologic Balance	N - Signs and Markers		
Y - Gen. Compliance With Mine Plan	N - Support Facilities Not On-site		
N - Other	N - Special Categories Of Mining		
N - Processing Waste	N - Topsoil		

COMMENTS

This was partial inspection of the Williams Fork Mine; permit C1981044, operated by Moffat County Mining LLC. The inspection was conducted, and the report prepared by me, Robin Reilley of the DRMS. No mine representative was present during the inspection. Conditions were cloudy. Snow covered the site.

PERMITTING ACTIONS in PROGRESS:

RN8 decision Issued.

INSPECTION

GENERAL MINE PLAN COMPLIANCE:

Reclamation is progressing as permitted. Facilities have been removed throughout the site and reclamation has been completed.

ROADS – Rule 4.03

Construction 4.03.1(3) I 4.03.2(3); Drainage 4.03.1(4) I 4.03.2(4); Surfacing and Maintenance 4.03.1(5) and (6) I 4.03.2(5) and (6); Reclamation 4.03.1(7) I 4.03.2(7)

- The Haul Road at the entrance off State Highway 13 was snowbound rendering the site inaccessible.
- Access roads appeared snow covered throughout the site.
- Roads are not plowed in the winter, so the site is inaccessible.

INSPECTION, ENFORCEMENT and CIVIL PENALTIES – RULE 5 Inspections 5.02; Availability of Records

Permit documents were not inspected as this was a partial inspection.

DOCUMENTS RECEIVED

None

Number of <u>Partial</u> Inspection this Fiscal Year: 6 Number of <u>Complete</u> Inspections this Fiscal Year: 3

OTHER (SPECIFY)

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS



Photo 1: Mine identification sign at the site entrance off highway 13.

Number of <u>Partial</u> Inspection this Fiscal Year: 6 Number of <u>Complete</u> Inspections this Fiscal Year: 3