



April 1, 2024

Tyson Geist
SEMA Construction, Inc.
7353 S. Eagle St
Centennial, CO 80112

RE: Motorcross Borrow Pit (M-2022-006)
Receipt of Corrective Action Documentation

Dear Mr. Geist,

The Division received your above referenced response to the Compliance Problems cited in the Division's inspection report that was conducted on March 7, 2024. The status of the corrective actions regarding the cited problems are as follows:

Problem: The affected area boundary markers are missing or incorrectly placed. This is a problem for failure to maintain boundary markers around the affected area as required by Section 3.1.12(2) of the rule.

Corrective action: The operator shall conduct a survey and replace the boundary markers in the correct location(s). The operator shall provide proof to the Division that this has been done by the corrective action date.

The Division received photo documentation of the boundary markers at the site and the problem is considered resolved.

If you have any questions, please contact me at (720) 774-0040 or brock.bowles@state.co.us.

Sincerely,

Brock Bowles
Environmental Protection Specialist

