

STATE OF
COLORADO

Reilley - DNR, Robin <robin.reilley@state.co.us>

Review 2024 Q1 Pond Inspections Yoast and Seneca IIW

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Wed, Apr 17, 2024 at 9:08 AM

To: "Kawcak, Miranda" <MKawcak@peabodyenergy.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Morning Miranda,

Thank you for the timely submission of the 2024 Q1 Sediment Pond Reports for the Yoast and Seneca IIW mine sites. Please find DRMS's reviews of Sediment Pond reports.

The Division has no concerns at this time.

Thank you

Robin Reilley, M.S. GISP
Environmental Protection Specialist II



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P [303.866.3567](tel:303.866.3567) ext 8105 |


F [303.832.8106](tel:303.832.8106)


Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203

Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | <http://mining.state.co.us>

2 attachments

 **Review_Ponds_2024_Q1_Yoast.pdf**
235K

 **Review_Ponds_2024_Q1_Seneca.pdf**
242K



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

17 April 2024

Miranda Kawcak
Environmental Manger
Peabody, Colorado Operations

Re: Seneca II West (Permit No. C1982057)
Review Impoundment Report 2024 Q1

Dear Ms. Kawcak:

Thank you for your timely submittal of the 2024 quarter one pond reports for the Seneca IIW Mine. The Colorado Division of Reclamation, Mining and Safety (The Division) received the above referenced reports on 15 April 2024. Sediment pond inspections were conducted by Jason Herden of Seneca Coal Company on 26 March 2024. The report complies with the applicable sections of Rule 4.05.9.

Ponds were snow covered at the time of inspection. The following ponds were discharging at the time of inspection:

<i>Pond</i>	<i>Gallons per Minute (gpm)</i>
006	32.3
016	23.7

Sediment levels were acceptable, and no maintenance items were identified.

The following structures have achieved bond release:

- Ponds 005, 009,
- Stock Tanks T-1, T-5, T-18, T-20, T-22, T-24, T-25, T-26 and T-27

Monitoring items comprise a known slump at Pond 006, a spring near the Pond 005 dam, and an occasional seep at Pond 016. DRMS understands that Seneca Coal Company monitors these items on a regular basis.

Sincerely,

Robin Reilley, M.S. GISP
Environmental Protection Specialist II
Robin.reilley@state.co.us

