

Bowie No. 1 Mine PO Box 1488 Paonia, CO. 81428 (970)986-6236

April 23, 2024

Mr. Rob Zuber Department of Natural Resources Division of Reclamation, Mining and Safety 1313 Sherman Street, Room 215 Denver, CO. 80203

RE: Bowie Resources LLC Bowie No. 1 Mine

DRMS Permit No. C-1981-038 Quarterly Pond Inspection Reports

Dear Mr. Zuber:

Find enclosed Bowie No. 1 Mine Pond inspection reports for the 1st quarter of 2024. If you have any questions or concerns regarding this submittal, contact me at (970)986-6236.

Sincerely;

Basil R. Bear Mine Manager

Bowie Resources LLC	,			
Bowie #1 Mine				
Sedimentation Pond				
Loadout Pond				
Quarter:	1			
Inspection Date:	25-Mar-24			
Inspected By:	brb			
,				
Primary Elevation:	5724.00			
Cleanout Elevation:	5721.00			
Approximate Water Elevation at Time of Inspection:			DRY	
Approximate Sediment Ele	evation at Time of Inspection	n:	5720.00'	
Outflow (C.F.S.)			0.00	
Features:			Comments	
Rills & Gullies on Embankı	ment	No		
Inadequate Vegetation		No		
Outlet Channel Erosion		No		
Burrows		No		
Other				
Structural:				
Differential Settling		No		
Cracks or Slides		No		
Seepage		No		
Other				
Appurtenant Structu	res			
Defective Spillway		No		
Dewatering Device Clogge	ed	No		
Faulty Gates, Baffles, Pumps		No		
		Gate Closed		
Additional Comment	ts			

Bowie Resources LLC				·
Bowie #1 Mine				
Sedimentation Pond				
Highway Pond				
Quarter:	1			
	<u>'</u> 25-Mar-24			
Inspected By:	brb			
тороской Бу.	DID			
Primary Elevation:	5734.00			
Cleanout Elevation:	5734.00			_
Approximate Water Elevation	at Time of I	nspection:	DR	Υ
Approximate Sediment Elevat	tion at Time	of Inspection:	5727.	00'
Outflow (C.F.S.)			0.00	0
				<u> </u>
Features:			Comm	ents
Rills & Gullies on Embankme	nt	No		_
Inadequate Vegetation		No		
Outlet Channel Erosion		No		
Burrows		No		•
Other				
Structural:				
Differential Settling		No		
Cracks or Slides		No		-
Seepage		No		-
Other				
		•		
Appurtenant Structures	S			
Defective Spillway		No		
Dewatering Device Clogged		No		
Faulty Gates, Baffles, Pumps		No		
Other				
Additional Comments				
				

Bowie Resources LLC	,				
Bowie #1 Mine					
Sedimentation Pond					
WM WS-1 Pond					
Quarter:	1				
Inspection Date:	25-Mar-24				
Inspected By:	brb				
D:	7.004.50				
Primary Elevation:	7,064.50				
Cleanout Elevation:	7,064.50		1	DDV	
Approximate Water Elevat				DRY	
Approximate Sediment Ele	evation at Time	of Inspection:		7061.00'	
Outflow (C.F.S.)				0.00	
Features:	Features:			Comments	
Rills & Gullies on Embankı	ment		No		
Inadequate Vegetation			No		
Outlet Channel Erosion			No		
Burrows			No		
Other			No		
Structural:					
Differential Settling			No		
Cracks or Slides			No		
Seepage		No			
Other					
A					
Appurtenant Structures		No			
Defective Spillway		No No			
Dewatering Device Clogged		No			
Faulty Gates, Baffles, Pumps Other		Gate Closed			
Other			Gale Closed		
Additional Comment					
Additional Comment					

Bowie Resources LLC	;				
Bowie #1 Mine					
Sedimentation Pond					
WM WS-2 Pond					
Quarter:	1				
Inspection Date:	25-Mar-24				
Inspected By:	brb				
Primary Elevation:	7095.80				
Cleanout Elevation:	7095.80				
Approximate Water Elevat		nspection:		DRY	
Approximate Valor Elevation at Time of Inspection:			:	7091.00'	
Outflow (C.F.S.)		1		0.00	
(=/				,	
Features:			Comments		
Rills & Gullies on Embankı	ment		No		
Inadequate Vegetation			No		
Outlet Channel Erosion			No		
Burrows			No		
Other			No		
Structural:					
Differential Settling		No			
Cracks or Slides			No		
Seepage		No			
Other					
Appurtenant Structu	res				
Defective Spillway		No]		
Dewatering Device Clogged		No			
Faulty Gates, Baffles, Pur			No		
Other		Gate Open			
			•	•	
Additional Comment	ts				