

STATE OF
COLORADO

Reilley - DNR, Robin <robin.reilley@state.co.us>

Compliance Reports 2024 Q1 Williams Fork Mine

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Wed, May 1, 2024 at 2:29 PM

To: "Kawcak, Miranda" <MKawcak@peabodyenergy.com>, "Howard, Michael" <MHoward@peabodyenergy.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Morning Miranda,

Please find DRMS's review of the below mentioned compliance reports for the Williams Fork mine.

- DMR's
- Sediment Ponds
- Refuse Pile

No concerns were noted.

Thank you for the timely submission of the reports.

Robin Reilley, M.S. GISP
Environmental Protection Specialist IICOLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P 303.866.3567 ext 8105 |

F 303.832.8106

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203

Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | <http://mining.state.co.us>

3 attachments

WastePile_Review_2024Q1.pdf
248K **Review_Ponds_2024_Q1_WF.pdf**
250K **Review_DMR_WF_2024_Q1.pdf**
222K



1 May 2024

Ms. Miranda Kawcak
Moffat County Mining, LLC.
29515 Routt County Road #27
Oak Creek, CO 80467

**RE: Refuse Pile Report Review: 2024 Quarter 1
Williams Fork Mines, Permit No. C1981044**

Dear Ms. Kawcak;

The Colorado Division of Reclamation, Mining and Safety has completed its review of the above referenced report. Please see the Division's findings below regarding the report's compliance with the following Rules.

1. 4.10.2(1)
 - a. The mine waste bank was inspected, on behalf of the person conducting surface coal mining operations, by a qualified registered engineer, or other qualified professional specialist.
 - b. The waste bank was capped in December 2020 and topsoil was placed on the surface of the waste pile.
 - c. The #9 excavation waste disposal area was reclaimed in 2009.
2. 4.10.2(2)
 - a. The submitted inspection report complies with the inspection requirement of rule 4.09.1(11).
 - o This was a quarterly inspection.
 - o The report indicated the stability of the fills was inspected and no appearances of instability, structural weakness or other hazardous conditions were noted. The inspection was conducted on 28 March 2024 and the report received by DRMS on 30 April 2024.
 - b. The stability of the fills was inspected. Tests were not necessary to evaluate any potential hazard to human life and property.
 - o Stability of the waste disposal areas was inspected, and problems were not identified. No maintenance items were noted.
 - c. Copies of the inspection findings shall be maintained at the mine site.
3. 4.10.2(3)

No potential hazards were noted in the above referenced refuse pile inspection report. Vegetation is establishing.

If you have any questions, please contact me, I am available.



Sincerely,

A handwritten signature in blue ink that reads "Robin Reilley". The signature is written in a cursive style with a long, sweeping underline.

Robin Reilley M.S. GISP
Environmental Protection Specialist II
Robin.reilley@state.co.us