

Gagnon - DNR, Nikie <nikie.gagnon@state.co.us>

RE: ASCI Turnpike Eastern Boundary

1 message

Greg Geras <GregG@asphaltspecialties.com> To: "Gagnon - DNR, Nikie" <nikie.gagnon@state.co.us> Fri, May 31, 2024 at 10:04 AM

Hi Nikie,

Our surveyor marked the property boundary yesterday, 5/30. Stakes with pink flagging show the property line is essentially just west of the Schell culvert feature and the mud flow did cross the boundary. Please find the attached photo log of what I observed yesterday from ASCI's property along with the surveyor's points (note: the "L" and "R" point descriptions are for lathe set along line and the others are property corners and section corners found).

As shown in Photo 6 (culvert circled), cleanup has progressed to a point where we can access the Schell culvert to clean it out. However, since it is off property, I wanted to contact you prior to initiating cleanup to verify proper procedure.

Please let me know when you would like to discuss.

Thanks,

Greg

ASPHALT SPECIALTIES CO. PHOTOGRAPH LOG					
Site Name:		Site Location:	Document:		
ASCI Turnpike Mining Resource		599 HWY 52, Erie, CO	Eastern Boundary Photos		
Photo No. 1 Direction P Taken: North	Date: 5/30/2024 Photo				
Description:					
Staked prope culvert	erty line by				

Photo No.	Date:	L STOR MAN WANT
2	5/30/2024	
Direction P	hoto	
Taken:		and the second
South		
Description:		
Staked property line by culvert to the south (stake south of mud flow in distance)		







Photo No.	Date:	
6	5/30/2024	
Direction P	hoto	
Taken:		
South		A Company of the second s
Description:		
Culvert installed on ASCI property to facilitate drainage.		



