

STATE OF  
COLORADO

Gagnon - DNR, Nikie &lt;nikie.gagnon@state.co.us&gt;

---

**RE: Turnpike Inspection Report**

1 message

---

**Greg Geras** <GregG@asphaltspecialties.com>  
To: "Gagnon - DNR, Nikie" <nikie.gagnon@state.co.us>

Mon, Jun 10, 2024 at 2:41 PM

Hi Nikie,

I was out of the office Thursday afternoon and Friday last week. Following up on the inspection report. Please find the attached photo log showing additional boundary markers (i.e., green t-posts with PVC caps) installed along the eastern boundary including the corners. This should address Problem #2. Please let me know if you have questions.

Thanks,

Greg

---

**From:** Gagnon - DNR, Nikie <nikie.gagnon@state.co.us>  
**Sent:** Thursday, June 6, 2024 3:18 PM  
**To:** Greg Geras <GregG@asphaltspecialties.com>  
**Subject:** Turnpike Inspection Report**[External Email]**

Hi Greg.

Please see the attached inspection report for the Turnpike Mining Resource site. Review the corrective actions and let me know if you have any questions.

Kind regards,

**Nikie Gagnon****Environmental Protection Specialist**

P 303.866.3567 x8126 | C 720.527.1640 | F 303.832.8106

Physical: [1313 Sherman Street, Room 215, Denver, CO 80203](#)

Mailing: DRMS Room 215, [1001 E 62nd Ave, Denver, CO 80216](#)


[nikie.gagnon@state.co.us](mailto:nikie.gagnon@state.co.us) | <https://www.drms.colorado.gov>

IMPORTANT NOTICE: This message is intended only for the addressee and may contain confidential, privileged information. If you are not the intended recipient, you may not use, copy or disclose any information contained in the message. If you have received this message in error, please notify the sender by reply e-mail and delete the message.




**ASCI-Turnpike Boundary Markers\_6-10-2024.pdf**

1238K

<b>Site Name:</b> ASCI Turnpike Mining Resource		<b>Site Location:</b> 599 Highway 52, Erie, CO	<b>Document:</b> 5/10/2024 Inspection - Corrective Action for Problem #2
<b>Photo No.</b> <b>1</b>	<b>Date:</b> 6/10/2024		
<b>Direction Photo Taken:</b>  North			
<b>Description:</b>  Boundary marker installed in the NE corner of the south half permit area.			

<b>Photo No.</b> <b>2</b>	<b>Date:</b> 6/10/2024	
<b>Direction Photo Taken:</b>  North		
<b>Description:</b>  Boundary markers installed along eastern boundary of the south half permit area.		

<b>Site Name:</b> ASCI Turnpike Mining Resource		<b>Site Location:</b> 599 Highway 52, Erie, CO	<b>Document:</b> 5/10/2024 Inspection - Corrective Action for Problem #2
<b>Photo No.</b> <b>3</b>	<b>Date:</b> 6/10/2024		
<b>Direction Photo Taken:</b>  North			
<b>Description:</b>  Boundary markers installed along eastern boundary of the south half permit area.			

<b>Photo No.</b> <b>4</b>	<b>Date:</b> 6/10/2024	
<b>Direction Photo Taken:</b>  West		
<b>Description:</b>  Boundary marker installed in the SE corner of the south half permit area.		