




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Centennial Uranium Project	MINE/PROSPECTING ID#: P-2008-043	MINERAL: Uranium	COUNTY: Weld
INSPECTION TYPE: Surety-Related Inspection	WEATHER: Clear	INSP. DATE: June 12, 2024	INSP. TIME: 10:00
OPERATOR: Powertech (USA) Inc.	OPERATOR REPRESENTATIVE: Peter Luthiger, Lisa Scheinost	TYPE OF OPERATION: MP - Mineral Prospecting	
REASON FOR INSPECTION: Surety Release Requested	BOND CALCULATION TYPE: None	BOND AMOUNT: \$71,400.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
INSPECTOR(S): Hunter Ridley	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: June 20, 2024	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>N</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>N</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>N</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>N</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

The Centennial Uranium Project Notice of Intent (NOI) was inspected by Hunter Ridley with the Division of Reclamation, Mining and Safety (Division) in response to a release request (SL-1) submitted to the Division on May 23, 2024. Lisa Scheinost and Peter Luthier with Powertech (USA) Inc. were present during the inspection. This inspection is considered nonconfidential due to the submittal of modification no. 1 (MD-01) on September 17, 2012.

The Centennial Uranium Project is a NOI to Prospect for in-situ uranium. The original NOI included exploration boreholes and groundwater observation wells. As of March 3, 2010, the Division has received the proper abandonment reports for all exploratory core holes and the required Well Construction and Test Reports have been received for all monitoring wells which will be permanent in final reclamation. The project area was inspected via existing Weld County roads and two-track ranch access roads. The project area was inspected from north to south via existing Weld County roads and two-track ranch access roads. Prior access approval was obtained for wells located on private property.

Over the course of the Division's previous two inspections of the site, all wells and abandoned borehole locations have been observed by the Division. A tabled list of these borehole and well locations is attached below.

When necessary, well locations have been protected by corral fencing or are within private property protected by barbed wire. All wells are sealed with a locked, metal cap. No erosion or sedimentation issues were noted. Wells sites are clear of drilling debris or trash. The surrounding vegetated areas were stable and had good cover. No new activity has occurred since the last inspection on October 25, 2019.

The Division currently holds a financial warranty amount of \$71,400.00 for this site. This amount will be subject to release back to the Operator with the approval of SL1.

Based on observations from this inspection, the Division will **approve** the full and final release of Permit P-2007-015, Centennial Uranium Project.

Representative photographs taken during the inspection has been included below. Responses to this inspection report should be directed to: Hunter Ridley at the Division of Reclamation, Mining and Safety, 1313 Sherman St., Room 215, Denver, CO 80203. Direct contact can be made by phone at 720-868-7757 or via email at hunter.ridley@state.co.us.

PHOTOGRAPHS



Figure 1: Several holes have been permanently abandoned via conversion to water wells.



Figure 2: Wells are protected by cattle guards.



Figure 3: Wells are secured with locks and labeled with small, metal plates.

Inspection Contact Address

Peter Luthiger, Lisa Scheinost
Powertech (USA) Inc.
101 N. Shoreline Blvd.
Corpus Christi, TX 78401