

July 2, 2024

Ms. Amy Yeldell Division of Reclamation, Mining and Safety 101 S. 3rd St., Suite 301, Grand Junction, CO 81501 Rm 215 1001 E. 62nd Ave, Denver CO 80216 <u>amy.yeldell@state.co.us</u>

Dear Ms. Yeldell,

This letter is in response to the DRMS Inspection Report dated October 24, 2023 and required corrective action.

The Problem, as outlined in the Inspection Report: The affected area boundary markers are insufficient to delineate the affected lands. This is a problem for failure to maintain boundary markers around the affected area as required by Section 3.1.12(2) of the rule.

The Corrective Actions: The operator shall 1) conduct a survey and replace the boundary markers in the correct location(s). 2) Provide a map which correlates to the photographic documentation of location points. 3) And include a cover letter declaring if all disturbance were contained within the permit boundary.

CDOT Maintenance in cooperation with the CDOT Region 3 Survey team have surveyed the permit area. Attached is a survey map with corresponding locations of all the posts. Also attached are photos of the posts in the field.

During the survey work, both CDOT Survey and Maintenance Crews observed that all mining disturbances were contained within the permit boundary. Stockpiles and jersey barriers observed at the time of inspection have all been removed from the site.

Please contact me for further information or if you have any questions.

Thank you,

ennifer Klaetsch

Jennifer Klaetsch



06/26/2024 DOVGLAS PASS PIT

Northing	Easting	Elv.	Code
78341.741'	107342.216'	6350.000'	1099
78616.912'	107209.671'	6350.000'	1099
79093.879'	107228.024'	6350.000'	1099
79477.082'	107686.836'	6350.000'	1099
79442.432'	108068.155'	6350.000'	1099
79014.390'	107992.708'	6350.000'	1099
78626.647'	107957.369'	6350.000'	1099
78601.469'	108021.689'	6350.000'	1099
78542.041'	107957.965'	6350.000'	1099
78627.796'	107934.946'	6350.000'	1099
78830.938'	107937.650'	6350.000'	1099
78837.053'	107697.028'	6350.000'	1099
78711.610'	107693.043'	6350.000'	1099
78867.725'	107473.972'	6350.000'	1099
79116.186'	107342.974'	6350.000'	1099
79264.046'	107441.933'	6350.000'	1099
79457.501'	107794.540'	6350.000'	1099
79312.426'	108045.240'	6350.000'	1099
78708.638'	107692.949'	6350.000'	1099
	78341.741' 78616.912' 79093.879' 79477.082' 79442.432' 79014.390' 78626.647' 78601.469' 78542.041' 78542.041' 78627.796' 78830.938' 78837.053' 78711.610' 78867.725' 79116.186' 79264.046' 79457.501'	78341.741'107342.216'78616.912'107209.671'79093.879'107228.024'79477.082'107686.836'79442.432'108068.155'79014.390'107992.708'78626.647'107957.369'78601.469'108021.689'78542.041'107957.965'78627.796'107934.946'78830.938'107937.650'78847.053'107697.028'78711.610'107693.043'7867.725'107473.972'79116.186'107441.933'79457.501'107794.540'79312.426'108045.240'	78341.741' 107342.216' 6350.000' 78616.912' 107209.671' 6350.000' 79093.879' 107228.024' 6350.000' 79477.082' 107686.836' 6350.000' 79477.082' 107686.836' 6350.000' 79442.432' 108068.155' 6350.000' 79014.390' 107992.708' 6350.000' 78601.469' 107957.369' 6350.000' 78601.469' 108021.689' 6350.000' 78542.041' 107957.965' 6350.000' 78830.938' 107937.650' 6350.000' 78837.053' 107697.028' 6350.000' 78711.610' 107693.043' 6350.000' 78667.725' 107473.972' 6350.000' 79116.186' 107342.974' 6350.000' 79264.046' 107441.933' 6350.000' 79312.426' 108045.240' 6350.000'

Shared with me > Douglas pit stake location - 🕾









