





MAP FEATURES			
PROPERTY BOUNDARY	PLANNED TOPSOIL STOCKPILES	TRAIL	
DISTURBANCE AREA	RECLAMATION AREAS	PERENNIAL STREAM	
XCEL ENERGY EASEMENT	BUILDING	INTERMITTENT STREAM	
TAILINGS IMPOUNDMENT	UNIMPROVED ROAD	ULTIMATE INTERCEPTOR CANAL	
LAKE / POND	IMPROVED ROAD	GRAVEL PIT	
EXISTING TOPSOIL STOCKPILES	CONVEYOR	AFFECTED LAND BOUNDARY	Contour Interval: 25 feet

REVISION	DATE	AUTHOR
Revised for 2013 Annual Report	2/27/14	MT
Revised for 2014 Annual Report	2/24/2015	MT
Updated dates for 2015 Annual Report	2/29/2016	MT
Updated dates for 2016 Annual Report	3/3/2017	TH
Updated dates and imagery	3/4/2019	AP
Updated dates for 2020 Annual Report	3/3/2021	MT
Updated dates for 2021 Annual Report	3/1/2022	MT
Updated dates for 2022 Annual Report	3/1/2022	MT
Updated dates for 2023 Annual Report	2/29/2024	MT
Updated Layer Display to show all Affected Lands Boundary Locations	07/18/2024	MT

Climax Molybdenum
A Freeport-McMoRan Company
HENDERSON OPERATIONS
1746 County Road
Empire, Colorado 80438

HENDERSON MILL
MLRB Permit No. M-77-342
Annual Reclamation Report
March 2024

DESIGNED BY:
DRAWN BY: MT(Aquionix)
DATE DRAWN: 3/4/11

SCALE: 1:20,000
COORD. SYSTEM: NAD_1983_UTM
Zone_13N

Aquionix
EHS Services

5545 W. 56th Ave.
Arvada, CO 80002
303.289.7820
www.aquionix.com

STATE OF
COLORADOGagnon - DNR, Nikie <nikie.gagnon@state.co.us>

RE: Annual Report Map - conveyor affected area boundary

1 message

Hamarat, Miguel <mhamarat@fmi.com>
To: "Gagnon - DNR, Nikie" <nikie.gagnon@state.co.us>

Wed, Jul 24, 2024 at 7:41 PM

Nikie,

Revised map attached. See you on Tuesday.

Regards,

Miguel

From: Gagnon - DNR, Nikie <nikie.gagnon@state.co.us>
Sent: Thursday, July 18, 2024 12:02 PM
To: Hamarat, Miguel <mhamarat@fmi.com>
Subject: Re: Annual Report Map - conveyor affected area boundary

Yes, you can submit a revised 2023 map to me. I'll upload it into the permit system with my email to explain the change to the map.

Nikie

On Thu, Jul 18, 2024 at 12:00 PM Hamarat, Miguel <mhamarat@fmi.com> wrote:

Nikie,

Good catch. I will get this updated. Did you want me to add this as a revision to the 2023 annual report submittal in ePermitting, assuming that option is available?

Miguel

From: Gagnon - DNR, Nikie <nikie.gagnon@state.co.us>
Sent: Wednesday, July 10, 2024 9:44 AM
To: Niggeler, Geoffrey <gniggele@fmi.com>; Hamarat, Miguel <mhamarat@fmi.com>
Subject: Annual Report Map - conveyor affected area boundary

Hi Geoff and Miguel.

CDPHE contacted me about the affected land boundary for the conveyor. They just wanted to know if the conveyor is bonded where it crosses land outside the property boundary in the attached Amendment 8 map. I confirmed that it is bonded. Sounds like a new person is reviewing the application and was just confirming the affected area boundary at the Mill.

However, the discussion prompted me to look at the annual report map submitted in March. I noticed that the annual report map shows this section of conveyor outside the affected land boundary. I think it would be a good idea to update the annual report map to show the affected acres boundary around the entire conveyor alignment because the public looks at these maps and would assume a portion of the conveyor is outside the bonded area.

--

Nikie Gagnon

Environmental Protection Specialist



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

Cell: 720.527.1640

Physical: [1313 Sherman Street, Room 215, Denver, CO 80203](#)

Address for FedEx, UPS, or hand delivery:

DRMS Room 215, [1001 E 62nd Ave, Denver, CO 80216](#)

nikie.gagnon@state.co.us | <https://www.drms.colorado.gov>



Appendix A Henderson Mill Annual Reclamation Report Map_Revised_07182024.pdf
3157K