

Culverts to be Removed at Closure

Updated: 7/31/2024

<i>Figure</i>	<i>Inlet</i>		<i>Length (ft)</i>	<i>Diameter (in)</i>	<i>Material</i>
	<i>Northing*</i>	<i>Easting*</i>			
F-04	7564.20	860.02	43.8	24	CMP
F-05	9413	-221	75	30	CMP
F-05	9878	-643	65	34	Wood
F-05	9937	-716	66	42	HDPE
F-05	10930	-1196	51	18	CMP
F-05	11654.51	-1646.32	58.7	18	CMP
F-05	18942	-3945	66	24	CMP
F-05	18717	-2943	25	24	CMP
F-05	18878	-2695	45	36	CMP
F-05	21150	-1080	50	36	CMP
F-05	22425	-337	45	24	CMP
F-06	23682	500	40	18	Steel
F-06	24340	894	30	18	ADS
F-06	24001	917	50	18	ADS
F-06	23608	859	65	18	CMP
F-06	23473	791	80	18	HDPE
F-06	24779	239	50	24	ADS
F-06	24764	-103	140	24	ADS
F-06	25009	-251	40	18	HDPE
F-06	25676	12	50	18	ADS
F-06	26159	-96	60	18	ADS
F-06	27450	-275	400	42	HDPE
F-06	25391	701	120	40	ADS
F-06	25755	611	40	18	ADS
F-06	25968	613	30	18	ADS
F-06	26000	608	30	18	ADS
F-06	26580	1089	60.65	18	ADS
F-06	27505	2317	40	24	ADS
F-06	26501	1104	81.3	18	ADS
F-07	15031	-6030	25	42	CMP
F-07	17447	-6445	92	12	Steel
F-07	17550	-6513	225	42	HDPE
F-07	17744	-7243	25	24	CMP