



STATE OF
COLORADO

Reilley - DNR, Robin <robin.reilley@state.co.us>

Review Q2 DMRs and Sed Pond reports

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Wed, Aug 7, 2024 at 12:16 PM

To: "Kawcak, Miranda" <MKawcak@peabodyenergy.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good afternoon Miranda,

Please find the above mentioned review for 2024 Q2 Seneca IIW mine site. DRMS has no concerns at this time.

Please let me know of any questions you may have.

Thank you

Robin Reilley, M.S. GISP
Environmental Protection Specialist II



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P [303.866.3567](tel:303.866.3567) |

F [303.832.8106](tel:303.832.8106)

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203

Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | <http://mining.state.co.us>

2 attachments



Review_DMR_Seneca_2024_Q2.pdf
215K



Review_Ponds_2024_Q2_Seneca.pdf
392K



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

7 August 2024

Miranda Kawcak
Environmental Manager
Peabody, Colorado Operations

Re: Seneca II West (Permit No. C1982057)
Review Impoundment Report 2024 Q2

Dear Ms. Kawcak:

Thank you for your timely submittal of the 2024 quarter two pond reports for the Seneca IIW Mine. The Colorado Division of Reclamation, Mining and Safety (The Division) received the above referenced reports on 5 August 2024. Sediment pond inspections were conducted by Jason Herden of Seneca Coal Company on 10 and 11 June 2024. The report complies with the applicable sections of Rule 4.05.9.

Ponds were holding water at the time of inspection. The following ponds were discharging at the time of inspection:

<i>Pond</i>	<i>Gallons per Minute (gpm)</i>
006	104.4
015	44.3
016	138.6
017	58.6

Sediment levels were acceptable, and no maintenance items were identified.

The following structures have achieved bond release:

- Ponds 005, 009,
- Stock Tanks T-1, T-5, T-18, T-20, T-22, T-24, T-25, T-26 and T-27

Monitoring items comprise a known slump at Pond 006, a spring near the Pond 005 dam, and an occasional seep at Pond 016. DRMS understands that Seneca Coal Company monitors these items on a regular basis.

Sincerely,

Robin Reilley, M.S. GISP
Environmental Protection Specialist II
Robin.reilley@state.co.us

