



September 3, 2024

Basil Bear  
Bowie Resources, LLC  
P.O. Box 1488  
Paonia, CO 81428

**Re: Bowie No. 1 Mine, Permit C-1981-38,  
Second Adequacy Letter for TR-66**

Dear Mr. Bear:

Today, the division received the adequacy responses for Technical Revision No. 66 (TR-66).

The Division has the following adequacy items that must be addressed prior to our approval of TR-66.

1. No additional response required.
2. On Map 07, please clarify the symbology for SAEs. It appears that green hatching is used in some locations but not other locations. Please check that all symbology is correct and consistent on this map.

**This is still not clear on the revised map. It appears that green hatching is used to show features such as grass filters or other BMPs. Should the hatching illustrate the SAEs themselves? To the Division, SAEs are the drainage areas above the sediment control best management practices (BMPs), not just the BMPs. Please update the map to clearly show the SAE areas and include different symbols for grass filters and other BMPs.**

3. No additional response required.
4. No additional response required.
5. No additional response required.
6. No additional response required.
7. No additional response required.
8. No additional response required.



Bowie Resources, LLC

Page 2 of 2

Adequacy review of TR-66 for the Bowie No. 1 Mine

Please call or e-mail me with any questions related to this matter.

Thank you,

A handwritten signature in blue ink, appearing to read "Robert D. Zuber".

Robert D. Zuber, P.E.

Environmental Protection Specialist

Cc via email: Ryan Wilson, Wolverine Fuels  
Tamme Bishop, J.E. Stover & Associates, Inc.