

Reilley - DNR, Robin <robin.reilley@state.co.us>

Review DMRS 2024 July

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us> Mon, Sep 9, 2024 at 7:46 AM To: Graham Roberts <graham.roberts@trappermine.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Morning Graham,

Please find DRMS's review of the 2024 July DMRs for Trapper Mine. The Division has no concerns.

Thank you

Robin Reilley, M.S. GISP Environmental Protection Specialist II



COLORADO Division of Reclamation, Mining and Safety Department of Natural Resources

P 303.866.3567 F 303.832.8106 Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203 Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216 robin.reilley@state.co.us | http://mining.state.co.us

Review_DMR_2024_07July_Trapper.pdf



Graham Roberts Trapper Mining Inc. P.O. Box 187 Craig, CO 81626

9 September 2024

Re: Trapper Mine (Permit No. C1981-010) Review of DMR's 2024 July

Dear Mr. Roberts:

The Division has received and reviewed the 2024 July monthly, Monitoring Reports (DMRs), including the acute monthly WET testing results for the Trapper Mine. The DMRs were received electronically by the Division on 27 August 2024. Thank you for your timely submittal of this information. Trapper submits DMRs to the Division, in accordance with Rule 4.05.13(2)(a)(iii).

Trapper reported the following outfalls discharged in June and over the quarter:

- Johnson System Pond #10, NPDS 001
- No Name Pond #5 NPDES 002
- East Pyeatt #2

Trapper reported that none of the outfalls requiring WET testing discharged. DMRs for discharging outfalls indicated that no parameters were exceeded. The Division notes that the Johnson System pH is at the upper limit of 9.0

The Division does not have any questions, concerns, or further comments at this time. If you have any questions or need additional information, please contact me.

Sincerely,

Robin Reilley, M.S. GISP Environmental Protection Specialist II Robin.reilley@state.co.us

