

**STATE OF  
COLORADO**

Reilley - DNR, Robin &lt;robin.reilley@state.co.us&gt;

---

## Review Yoast, Williams Fork and Peabody Sage Creek Compliance Reports

1 message

**Reilley - DNR, Robin** <robin.reilley@state.co.us>

Wed, Aug 7, 2024 at 3:59 PM

To: "Kawcak, Miranda" &lt;MKawcak@peabodyenergy.com&gt;, Robin Reilley - DNR &lt;robin.reilley@state.co.us&gt;

Good Afternoon Miranda,

Please find DRMS's review of the 2024 compliance reports for the above referenced sites. The Division has no concerns.

Thank you

**Robin Reilley, M.S. GISP**  
Environmental Protection Specialist II**COLORADO**  
Division of Reclamation,  
Mining and Safety  
Department of Natural ResourcesP [303.866.3567](tel:303.866.3567) |F [303.832.8106](tel:303.832.8106)

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203

Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

[robin.reilley@state.co.us](mailto:robin.reilley@state.co.us) | <http://mining.state.co.us>

---

### 6 attachments

**Review\_DMR\_Yoast\_2024\_Q2.pdf**

212K

**Review\_Ponds\_2024\_Q2\_Yoast.pdf**

237K

**WastePile\_Review\_2024Q2\_WF.pdf**

216K

**Review\_DMR\_2024\_Q2\_WF.pdf**

213K

**Review\_Ponds\_2024\_Q2\_WF.pdf**

305K

**Review\_DMR\_2024\_\_05May\_SgCk.pdf**

266K



**COLORADO**  
Division of Reclamation,  
Mining and Safety  
Department of Natural Resources

7 August 2024

Ms. Miranda Kawcak  
Moffat County Mining, LLC.  
29515 Routt County Road #27  
Oak Creek, CO 80467

**RE: Refuse Pile Report Review: 2024 Quarter 2  
Williams Fork Mines, Permit No. C1981044**

Dear Ms. Kawcak;

The Colorado Division of Reclamation, Mining and Safety has completed its review of the above referenced report. Please see the Division's findings below regarding the report's compliance with the following Rules.

1. 4.10.2(1)
  - a. The mine waste bank was inspected, on behalf of the person conducting surface coal mining operations, by a qualified registered engineer, or other qualified professional specialist.
  - b. The waste bank was capped in December 2020 and topsoil was placed on the surface of the waste pile.
  - c. The #9 excavation waste disposal area was reclaimed in 2009.
2. 4.10.2(2)
  - a. The submitted inspection report complies with the inspection requirement of rule 4.09.1(11).
    - o This was a quarterly inspection.
    - o The report indicated the stability of the fills was inspected and no appearances of instability, structural weakness or other hazardous conditions were noted. The inspection was conducted on 25 June 2024 and the report received by DRMS on 5 August 2024.
  - b. The stability of the fills was inspected. Tests were not necessary to evaluate any potential hazard to human life and property.
    - o Stability of the waste disposal areas was inspected, and no problems were identified. No maintenance items were required at the time of inspection.
  - c. Copies of the inspection findings shall be maintained at the mine site.
3. 4.10.2(3)

No potential hazards were noted in the above referenced refuse pile inspection report. Vegetation is establishing.

Sincerely,

Robin Reilley M.S. GISP  
Environmental Protection Specialist II

