



STATE OF  
COLORADO

Reilley - DNR, Robin <robin.reilley@state.co.us>

---

## Review Compliance Reports 2024 Q3

1 message

**Reilley - DNR, Robin** <robin.reilley@state.co.us>

Fri, Sep 27, 2024 at 8:52 AM

To: Graham Roberts <graham.roberts@trappermine.com>, Tonia Perkins <tonia.perkins@trappermine.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Colleagues,

Please find DRMS's review of Trappers 2024 Q3 DMRs, Sediment Pond and Horse Gulch Fill reports. DRMS has no concerns at this time.

Thank you for your timely submission of the reports.

Robin Reilley, M.S. GISP  
Environmental Protection Specialist II



**COLORADO**  
Division of Reclamation,  
Mining and Safety  
Department of Natural Resources

P [303.866.3567](tel:303.866.3567) |

F [303.832.8106](tel:303.832.8106)

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203

Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216  
[robin.reilley@state.co.us](mailto:robin.reilley@state.co.us) | <http://mining.state.co.us>

---

### 3 attachments



**Review\_HGFill\_2024\_Q3\_Trapper.pdf**  
240K



**Review\_DMR\_2024\_08August\_Trapper.pdf**  
269K



**SedPondReview\_2024\_Q3\_Trapper.pdf**  
242K



**COLORADO**  
Division of Reclamation,  
Mining and Safety  
Department of Natural Resources

Graham Roberts  
Trapper Mining Inc.  
P.O. Box 187  
Craig, CO 81626

27 September 2024

**Re: Trapper Mine (Permit No. C1981-010)**  
**Review of DMR's 2024 August**

Dear Mr. Roberts:

The Division has received and reviewed the 2024 August monthly, Monitoring Reports (DMRs), including the acute monthly WET testing results for the Trapper Mine. The DMRs were received electronically by the Division on 17 September 2024. Thank you for your timely submittal of this information. Trapper submits DMRs to the Division, in accordance with Rule 4.05.13(2)(a)(iii).

Trapper reported the following outfalls discharged in June and over the quarter:

- Johnson System Pond #10, NPDS 001
- No Name Pond #5 NPDES 002
- East Pyeatt #2
- Middle Flume #20
- East Middle Flume #21

Trapper reported that none of the outfalls requiring WET testing discharged. DMRs for discharging outfalls indicated that no parameters were exceeded. The Division notes that the Johnson System pH registered at the upper limit of 9.0.

The Division does not have any questions, concerns, or further comments at this time. If you have any questions or need additional information, please contact me.

Sincerely,

Robin Reilley, M.S. GISP  
Environmental Protection Specialist II  
[Robin.reilley@state.co.us](mailto:Robin.reilley@state.co.us)

