





October 9th, 2024

State of Colorado Division of Reclamation, Mining & Safety 1313 Sherman St., Room 215 Denver, CO 80203

Attn: Environmental Protection Specialist

Re: GCC Energy, LLC, King II Mine

CDRMS Permit # C-1981-035

Re: 3rd Quarter 2024 Surface Subsidence Inspections 3rd Quarter 2024 Huntington Ditch Inspections

Mr. Wein:

No subsidence issues have been noticed in the mined-out areas west of Pine Gulch on the Huntington ranch property. Dan Huntington has not mentioned any subsidence related issues on other areas of his property. No additional subsidence has been noted on the Crawford Ranch property and GCC personnel will be notified if they feel action is required.

Please contact me at the contact information in the header, or Jordan McCourt at jmccourt@gcc.com if you have any questions or require any additional information.

Sincerely,

Michael Dickson