

Bowie No. 1 Mine PO Box 1488 Paonia, CO. 81428 (970)986-6236

October 14, 2024

Mr. Rob Zuber Department of Natural Resources Division of Reclamation, Mining and Safety 1313 Sherman Street, Room 215 Denver, CO. 80203

RE: Bowie Resources LLC
Bowie No. 1 Mine
DRMS Permit No. C-1981-038

DRMS Permit No. C-1981-038 Quarterly Pond Inspection Reports

Dear Mr. Zuber:

Find enclosed Bowie No. 1 Mine Pond inspection reports for the 3rd quarter of 2024. If you have any questions or concerns regarding this submittal, contact me at (970)986-6236.

Sincerely;

Basil R. Bear Mine Manager

Bowie Resources LL0	 C				
Bowie #1 Mine					
Sedimentation Pond					
Codimonitation i ond					
Loadout Pond					
Quarter:	3				
Inspection Date:	26-Sep-24				
Inspected By:	brb				
		ı			
Primary Elevation:	5724.00				
Cleanout Elevation:	5721.00				
Approximate Water Eleva	tion at Time of I	nspection:		DRY	
Approximate Sediment El			:	5720.00'	
Outflow (C.F.S.)				0.00	
Features:				Comments	
Rills & Gullies on Embank	ment		No		
Inadequate Vegetation			No		
Outlet Channel Erosion			No		
Burrows			No		
Other					
Structural:					
Differential Settling			No		
Cracks or Slides			No		
Seepage			No		
Other					
Appurtenant Structu	ures		•		
Defective Spillway			No		
Dewatering Device Clogge			No		
Faulty Gates, Baffles, Pumps			No		
Other			Gate Closed		_
Additional Commen	ts				

Bowie Resources LLC				
Bowie #1 Mine				
Sedimentation Pond				
Highway Pond				
Quarter:	3			
Inspection Date: 26-Se	ep-24			
Inspected By: b	rb			
Primary Elevation: 5	5734.00			
-	734.00			
Approximate Water Elevation at T	•		DRY	
Approximate Sediment Elevation			5727.00'	
Outflow (C.F.S.)	•		0.00	
Features:			Comments	
Rills & Gullies on Embankment		No		
Inadequate Vegetation		No		
Outlet Channel Erosion		No		
Burrows		No		
Other				
Structural:				
Differential Settling		No		
Cracks or Slides		No		
Seepage		No		
Other				
Appurtenant Structures				
Defective Spillway		No		
Dewatering Device Clogged		No		
Faulty Gates, Baffles, Pumps		No		
Other				
Additional Comments				

Bowie Resources LLC					
Bowie #1 Mine					
Sedimentation Pond					
WM WS-1 Pond					
Quarter:	3				
Inspection Date:	26-Sep-24				
Inspected By:	brb				
Drim and Elevation	7.064.50				
Primary Elevation:	7,064.50				
	Cleanout Elevation: 7,064.50 Approximate Water Elevation at Time of Inspection: DRY				
Approximate Sediment Ele				7061.00'	
Outflow (C.F.S.)	evation at Time of	півресцоп.		0.00	
Outilow (C.1 .5.)				0.00	
Features:		_		Comments	
Rills & Gullies on Embank	ment		No		
Inadequate Vegetation			No		
Outlet Channel Erosion			No		
Burrows			No		
Other			No		
Structural:					
Differential Settling			No		
Cracks or Slides			No		
Seepage			No		
Other					
A					
Appurtenant Structu	ires	1	1		
Defective Spillway	1		No		
Dewatering Device Clogged			No		
Faulty Gates, Baffles, Pumps			No		
Other		•	Gate Closed		
Additional Commen	 te				
Additional Commett					

Bowie Resources LLC	,				
Bowie #1 Mine	•				
Sedimentation Pond					
oodiiiioiitatioiiii oila					
WM WS-2 Pond					
Quarter:	3				
Inspection Date:	26-Sep-24				
Inspected By:	brb				
Primary Elevation:	7095.80				
Cleanout Elevation:	7095.80		-		
Approximate Water Eleva	tion at Time of I	nspection:		DRY	
Approximate Sediment Ele	evation at Time	of Inspection:		7091.00'	
Outflow (C.F.S.)				0.00	
Features:			1	Comments	
Rills & Gullies on Embank	ment		No		
Inadequate Vegetation			No		
Outlet Channel Erosion			No		
Burrows			No		
Other			No		
Cturretruel					
Structural:					
Differential Settling			No		
Cracks or Slides			No		
Seepage			No		
Other					
Appurtenant Structu	Iros				
Defective Spillway	11 63		No		
Dewatering Device Clogged			No		
Faulty Gates, Baffles, Pumps			No		
Other			ate Open		
0.1101			ato opon		
Additional Commen	ts				