




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: San Juan Silver Project	MINE/PROSPECTING ID#: P-2008-037	MINERAL: Silver and gold	COUNTY: Mineral
INSPECTION TYPE: Mineral Prospect Inspection	WEATHER: Clear	INSP. DATE: September 25, 2024	INSP. TIME: 13:00
OPERATOR: Rio Grande Silver, Inc.	OPERATOR REPRESENTATIVE: Randy McClure	TYPE OF OPERATION: MP - Mineral Prospecting	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: None	BOND AMOUNT: \$5,826.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
INSPECTOR(S): Todd Jesse	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: October 23, 2024	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>N</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>N</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the normal monitoring program established by the Colorado Division of Reclamation Mining and Safety's Active Mines Program. The San Juan Silver Project is listed as an active Notice of Intent to Conduct Prospecting Operations (NOI) located approximately 1 mile north of Creede, CO in Mineral County at an elevation of approximately 11,000 feet. This site consists of 2.1 acres to support exploratory drilling. Randy McClure, a representative of Rio Grande Silver, Inc. accompanied the inspection. The Division holds a \$5,826.00 Financial Warranty for the site. A reclamation cost estimate was not performed as a result of this inspection.

The NOI consists of 6 pads to support the drilling operation. Of those 6 pads, the only BD-6 has not been reclaimed. BD-1 through BD-4 and their associated road have been reclaimed. Vegetation is well established in the reclaimed area boulders have been placed to prevent disturbance from the public. No state listed invasive species were identified in the reclaimed area. Pad BD-5 was never constructed. Pad BD-6 has not yet been reclaimed. The access road continues past the pad to the Bulldog Project NOI. The BD-6 pad was being used for a water storage and transfer station for work at the Bulldog Project NOI but is not currently in use. The pad is leveled and cleared of vegetation. The cut slope on the western edge of the pad was stable and no evidence of settling, slumping or erosion was observed. The pad exhibits positive drainage and no impounded water was observed on the pad. The operator would like to keep the NOI open for further projects and does not intend to reclaim the pad at this time.

Photos that show the conditions observed during the inspection are included at the end of this report.

No problems or violations were noted or observed during the September 25, 2024 inspection.

All responses to this report should be directed to Todd Jesse with the Division's Active Mines Program at DRMS, Room 215, 1001 E 62nd Ave. Denver, CO 80216. Direct contact can be made at the Division's Grand Junction Field Office, by phone at 720-688-0626 or by email at todd.jesse@state.co.us.

PHOTOGRAPHS



Photo 1: View to the north of the BD-6 pad.

Inspection Contact Address

Randy McClure
Rio Grande Silver, Inc.
112 E. 12th Street
Creede, CO 81130