

# MINERALS PROGRAM INSPECTION REPORT PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

N	MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
P	P-2010-015	Zinc, lead, gold and	Mineral
WEATHER: Clear		INSP. DATE:	INSP. TIME:
		September 25, 2024	11:30
OPERATOR REPRESENTATIVE:		TYPE OF OPERATION:	
Randy McClure		MP - Mineral Prospecting	
	BOND CALCULATION TYPE:	BOND AMOUNT	•
Normal I&E Program		\$34,500.00	
DATE OF COMPLAINT:		JOINT INSP. AGENCY:	
NA		None	
INSPECTOR'S SIGNATURE:		SIGNATURE DATE:	
		October 23, 2024	
Tollo			
ICOCK CASSE			
	F V	OPERATOR REPRESENTATIVE: Randy McClure  BOND CALCULATION TYPE: None  POST INSP. CONTACTS: None	P-2010-015  WEATHER: Clear  OPERATOR REPRESENTATIVE: Randy McClure  BOND CALCULATION TYPE: None  POST INSP. CONTACTS: None  INSPECTOR'S SIGNATURE:  Zinc, lead, gold and some inspector in the post in the pos

#### **GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>N</u>	(FN) FINANCIAL WARRANTY <u>N</u>	(RD) ROADS <u>N</u>
(HB) HYDROLOGIC BALANCE <u>Y</u>	(BG) BACKFILL & GRADING $\underline{\mathbf{N}}$	(EX) EXPLOSIVES <u>N</u>
(PW) PROCESSING WASTE/TAILING N	(SF) PROCESSING FACILITIES $\underline{N}$	(TS) TOPSOIL <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- Y	(FW) FISH & WILDLIFE $\underline{N}$	(RV) REVEGETATION $\underline{\mathbf{Y}}$
(SM) SIGNS AND MARKERS <u>N</u>	(SP) STORM WATER MGT PLAN N	(RS) RECL PLAN/COMP N
(ES) OVERBURDEN/DEV. WASTE N	(SC) EROSION/SEDIMENTATION $\underline{N}$	(ST) STIPULATIONS $\underline{N}$
(AT) ACID OR TOXIC MATERIALS N	(OD) OFF-SITE DAMAGE <u>N</u>	

 $Y = Inspected \ / \ N = Not \ inspected \ / \ NA = Not \ applicable \ to \ this \ operation \ / \ PB = Problem \ cited \ / \ PV = Possible \ violation \ violation \ cited \ / \ PV = Possible \ violation \$ 

### **OBSERVATIONS**

This inspection was conducted as part of the normal monitoring program established by the Colorado Division of Reclamation Mining and Safety's Active Mines Program. The West Equity Project is listed as an active Notice of Intent to Conduct Prospecting Operations (NOI) located approximately 6 miles north of Creede, CO in Mineral County at an elevation of approximately 11,200 feet. Randy McClure, a representative of Rio Grande Silver, Inc. accompanied the inspection. The Division holds a \$34,500.00 Financial Warranty for the site. A reclamation cost estimate was not performed as a result of this inspection.

The NOI consists of 5 newly permitted pads that have not yet been disturbed, 2 reclaimed surface pads and a reclaimed access road. The reclaimed road to pads WE-1 and WE-2 were observed. The road has been graded to an approximate original contour and there are no sign of erosion or instability. Vegetation is well established and blends very well with surrounding undisturbed area. No state listed invasive species were identified in the reclaimed area. The undisturbed pads in the Rat Creek drainage were also observed.

Photos that show the conditions observed during the inspection are included at the end of this report.

No problems or violations were noted or observed during the September 25, 2024 inspection.

All responses to this report should be directed to Todd Jesse with the Division's Active Mines Program at DRMS, Room 215, 1001 E 62<sup>nd</sup> Ave. Denver, CO 80216. Direct contact can be made at the Division's Grand Junction Field Office, by phone at 720-688-0626 or by email at todd.jesse@state.co.us.

## **PHOTOGRAPHS**



Photo 1: View to the north of culvert that conveys West Willow Creek under the access road.



Photo 2: View to the west of undisturbed URC5 pad.




Photo 3: View to the south of undisturbed URC4 and URC3 pads.

PERMIT #: P-2010-015 INSPECTOR'S INITIALS: TJ1 INSPECTION DATE: September 25, 2024

Inspection Contact Address Randy McClure Rio Grande Silver, Inc. 112 E. 12th Street Creede, CO 81130