

MINERALS PROGRAM INSPECTION REPORT PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE/PROSPECTING ID#:	MINERAL: COUNT	'Y:	
P-2012-008	Silver, gold, lead and Mineral		
WEATHER: Clear	INSP. DATE: INSP. T	IME:	
	September 25, 2024 10:00		
OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:		
Randy McClure MP - Mineral Pr		pecting	
BOND CALCULATION TYPE:	BOND AMOUNT:		
rmal I&E Program None		\$26,760.00	
POST INSP. CONTACTS:	JOINT INSP. AGENCY:	JOINT INSP. AGENCY:	
None	None	None	
INSPECTOR'S SIGNATURE:	SIGNATURE DATE:		
	October 22, 2024		
Talla			
ICUR CASSE			
	P-2012-008 WEATHER: Clear OPERATOR REPRESENTATIVE: Randy McClure BOND CALCULATION TYPE: None POST INSP. CONTACTS:	P-2012-008 WEATHER: Clear WEATHER: Clear OPERATOR REPRESENTATIVE: Randy McClure BOND CALCULATION TYPE: None POST INSP. CONTACTS: None INSP. DATE: INSP. T September 25, 2024 10:00 TYPE OF OPERATION: MP - Mineral Prospecting BOND AMOUNT: \$26,760.00 JOINT INSP. AGENCY: None INSPECTOR'S SIGNATURE: SIGNATURE DATE:	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>N</u>	(FN) FINANCIAL WARRANTY N	(RD) ROADS <u>N</u>
(HB) HYDROLOGIC BALANCE <u>Y</u>	(BG) BACKFILL & GRADING \underline{N}	(EX) EXPLOSIVES N
(PW) PROCESSING WASTE/TAILING N	(SF) PROCESSING FACILITIES \underline{N}	(TS) TOPSOIL <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- Y	(FW) FISH & WILDLIFE \underline{N}	(RV) REVEGETATION <u>Y</u>
(SM) SIGNS AND MARKERS <u>N</u>	(SP) STORM WATER MGT PLAN N	(RS) RECL PLAN/COMP N
(ES) OVERBURDEN/DEV. WASTE N	(SC) EROSION/SEDIMENTATION \underline{N}	(ST) STIPULATIONS <u>N</u>
(AT) ACID OR TOXIC MATERIALS N	(OD) OFF-SITE DAMAGE <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

PERMIT #: P-2012-008 INSPECTOR'S INITIALS: TJ1 INSPECTION DATE: September 25, 2024

OBSERVATIONS

This inspection was conducted as part of the normal monitoring program established by the Colorado Division of Reclamation Mining and Safety's Active Mines Program. The North Amethyst West is listed as an active Notice of Intent to Conduct Prospecting Operations (NOI) located approximately 6 miles northwest of Creede, CO in Mineral County at an elevation of approximately 11,250 feet. Randy McClure, a representative of Rio Grande Silver, Inc. accompanied the inspection. The Division holds a \$26,760.00 Financial Warranty for the site. A reclamation cost estimate was not performed as a result of this inspection.

The NOI consists of an access road and drill pad. The pad appears stable with no visible signs of erosion or slumping (Photo 1). The roadway is in good condition. Volunteer vegetation has grown along the roadway (Photo 2) and the operator fell trees along the road to prevent unauthorized access with motor vehicles. The access road is also secured by a gate off NFSR 503. No state listed invasive species were identified in the area. The operator would like to keep the NOI open for future exploration.

Photos that show the conditions observed during the inspection are included at the end of this report.

No problems or violations were noted or observed during the September 25, 2024 inspection.

All responses to this report should be directed to Todd Jesse with the Division's Active Mines Program at DRMS, Room 215, 1001 E 62nd Ave. Denver, CO 80216. Direct contact can be made at the Division's Grand Junction Field Office, by phone at 720-688-0626 or by email at todd.jesse@state.co.us.

PHOTOGRAPHS



Photo 1: View to the north of pad.



Photo 2: View to the south of access road to drill pad.

PERMIT #: P-2012-008 INSPECTOR'S INITIALS: TJ1 INSPECTION DATE: September 25, 2024

Inspection Contact Address Randy McClure Rio Grande Silver, Inc. P.O. Box 610 Creede, CO 81130

Enclosure

CC: