



**COLORADO**  
Division of Reclamation,  
Mining and Safety  
Department of Natural Resources

October 31, 2024

Rudy Torres  
J-Rude Inc  
1750 Rd. HH  
Lamar, CO 81052

**Re: J-Rude Site, Permit No. M-1989-009, Permit Boundary Markers Problem Abated**

Dear Mr. Torres:

On October 24, 2024, the Division of Reclamation Mining and Safety (Division) received your corrective action documentation for the following problems identified in the Division's October 18, 2024 inspection report:

**INSPECTION TOPIC: Signs & Markers**

**PROBLEM #2:** The affected area boundary markers are missing or incorrectly placed. This is a problem for failure to maintain boundary markers around the affected area as required by Rule 3.1.12(2).

**CORRECTIVE ACTIONS:** The operator shall conduct a survey and replace the boundary markers in the correct location(s). The operator shall provide proof to the Division that this has been done by the corrective action date. Such proof shall be in the form of photo documentation and GPS coordinates of the boundary markers.

**CORRECTIVE ACTION STATUS:** Abated. The operator provided GPS coordinates of the boundary markers at the site, this is supported by the submitted aerial image.

If you require additional information, or have questions or concerns, please feel free to contact me by phone at (720) 793-3031, or by email at [ursula.armstrong@state.co.us](mailto:ursula.armstrong@state.co.us).

Sincerely,

Ursula Armstrong  
Environmental Protection Specialist

Cc:  
Amy Eschberger, DRMS

