



STATE OF
COLORADO

Reilley - DNR, Robin <robin.reilley@state.co.us>

Reviews: Fill Report, Sed Ponds, DMRs 2024 Q3

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Fri, Nov 1, 2024 at 12:34 PM

To: "Kawcak, Miranda" <MKawcak@peabodyenergy.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Afternoon Miranda,

Please find the above referenced review of compliance documents for 2024 Q3 for the Williams Fork site. Thank you for your timely submission of the reports
I'm available to answer any questions or concerns

Thank you,

Robin Reilley, M.S. GISP
Environmental Protection Specialist II



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P [303.866.3567](tel:303.866.3567) |

F [303.832.8106](tel:303.832.8106)

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203

Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216
robin.reilley@state.co.us | <http://mining.state.co.us>

3 attachments



WastePile_Review_2024Q3_WF.pdf
214K



Review_Ponds_2024_Q3_WF.pdf
302K



Review_DMR_2024_Q3_WF.pdf
213K



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

1 November 2024

Ms. Miranda Kawcak
Moffat County Mining, LLC.
29515 Routt County Road #27
Oak Creek, CO 80467

**RE: Refuse Pile Report Review: 2024 Quarter 3
Williams Fork Mines, Permit No. C1981044**

Dear Ms. Kawcak;

The Colorado Division of Reclamation, Mining and Safety has completed its review of the above referenced report. Please see the Division's findings below regarding the report's compliance with the following Rules.

1. 4.10.2(1)
 - a. The mine waste bank was inspected, on behalf of the person conducting surface coal mining operations, by a qualified registered engineer, or other qualified professional specialist.
 - b. The waste bank was capped in December 2020 and topsoil was placed on the surface of the waste pile.
 - c. The #9 excavation waste disposal area was reclaimed in 2009.
2. 4.10.2(2)
 - a. The submitted inspection report complies with the inspection requirement of rule 4.09.1(11).
 - o This was a quarterly inspection.
 - o The report indicated the stability of the fills was inspected and no appearances of instability, structural weakness or other hazardous conditions were noted. The inspection was conducted on 26 September 2024 and the report received by DRMS on 31 October 2024.
 - b. The stability of the fills was inspected. Tests were not necessary to evaluate any potential hazard to human life and property.
 - o Stability of the waste disposal areas was inspected, and no problems were identified. No maintenance items were required at the time of inspection.
 - c. Copies of the inspection findings shall be maintained at the mine site.
3. 4.10.2(3)

No potential hazards were noted in the above referenced refuse pile inspection report. Vegetation is establishing.

Sincerely,

Robin Reilley M.S. GISP
Environmental Protection Specialist II

