



STATE OF
COLORADO

Simmons - DNR, Leigh <leigh.simmons@state.co.us>

C1983059, Terror Creek Loadout, November Inspection Report

1 message

Simmons - DNR, Leigh <leigh.simmons@state.co.us>
To: Doug Smith <Doug.Smith@oxbow.com>

Tue, Nov 19, 2024 at 12:27 PM

Attached

Leigh Simmons
Environmental Protection Specialist



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P [720.220.1180](tel:720.220.1180)

1313 Sherman Street, Room 215, Denver, CO 80203

leigh.simmons@state.co.us | <https://drms.colorado.gov>




INSP-REPORTC_C1983059_LDS_11192024104905.pdf
528K



PERMIT INFORMATION

Permit Number: C-1983-059 Mine Name: Terror Creek Loadout Operator: Oxbow Mining, LLC Operator Address: Mr Doug Smith PO Box 535 Paonia, CO 81434	County: Delta Operation Type: Loadout Permit Status: Active Ownership: Private
	Operator Representative Present: Doug Smith
Operator Representative Signature: (Field Issuance Only) 	

INSPECTION INFORMATION

Inspection Start Date: November 14, 2024 Inspection Start Time: 11:00 Inspection End Date: Inspection End Time:	Inspection Type: Coal Partial Inspection Inspection Reason: Normal I&E Program Weather: Clear
Joint Inspection Agency: None	Joint Inspection Contacts:
Post Inspection Agency: None	Post Inspection Contacts:
Inspector(s): Leigh Simmons	Inspector's Signature:  Signature Date: November 19, 2024

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection

N - Roads

N - Availability of Records

N - Reclamation Success

N - Backfill & Grading

N - Revegetation

N - Excess Spoil and Dev. Waste

N - Subsidence

N - Explosives

N - Slides and Other Damage

N - Fish & Wildlife

N - Support Facilities On-site

N - Hydrologic Balance

N - Signs and Markers

R - Gen. Compliance With Mine Plan

N - Support Facilities Not On-site

N - Other

N - Special Categories Of Mining

N - Processing Waste

N - Topsoil

COMMENTS

This was a partial inspection by Leigh Simmons of the Division of Reclamation, Mining and Safety (Division). The weather was clear and dry. The gate to the site was secure. There was no mining-related activity at the site, but the site was being used for the storage of equipment and materials for other industrial and commercial activities.

GENERAL MINE PLAN COMPLIANCE:

The containers used to buttress the rear of the temporary building had been removed, and the gravel from inside them had been stockpiled at the east end of the gravel pad. The fabric doors to the building had been completely removed and were expected to be replaced with solid doors.

The lower pad was secure behind a locked gate.

No further work had been completed to remove the power poles.

DOCUMENTS RECEIVED

N/A

OTHER (SPECIFY)

N/A

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

Number of Partial Inspection this Fiscal Year: 3

Number of Complete Inspections this Fiscal Year: 2

PHOTOGRAPHS



Figure 1: Gravel stockpiled on lower pad

Number of Partial Inspection this Fiscal Year: 3

Number of Complete Inspections this Fiscal Year: 2