

Reilley - DNR, Robin <robin.reilley@state.co.us>

Review DMRs 2024 October

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Wed, Nov 20, 2024 at 5:49 PM

To: Graham Roberts <graham.roberts@trappermine.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Evening Graham,

Please find DRMS's review of the 2024 October DMRs for Trapper Mine. The Division has no concerns.

Thank you


Robin Reilley, M.S. GISP Environmental Protection Specialist II



P 303.866.3567| F 303.832.8106

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203 Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | http://mining.state.co.us





Graham Roberts Trapper Mining Inc. P.O. Box 187 Craig, CO 81626

20 November 2024

Re: Trapper Mine (Permit No. C1981-010) Review of DMR's 2024 October

Dear Mr. Roberts:

The Division has received and reviewed the 2024 October Discharge Monitoring Reports (DMRs), including the acute monthly WET testing results for the Trapper Mine. The DMRs were received electronically by the Division on 20 November 2024. Thank you for your timely submittal of this information. Trapper submits DMRs to the Division, in accordance with Rule 4.05.13(2)(a)(iii).

Trapper reported the following outfalls discharged over the quarter:

- o No Name Pond #5 NPDES 002
- o East Pyeatt #2 NPDES 011
- o East Middle Flume NPDES 021

Trapper reported that none of the outfalls requiring acute or chronic WET testing discharged. DMRs for discharging outfalls indicated that no parameters were exceeded.

The Division does not have any questions, concerns, or further comments at this time. If you have any questions or need additional information, please contact me.

Sincerely,

Robin Reilley, M.S. GISP

Bobin Beiller

Environmental Protection Specialist II

Robin.reilley@state.co.us

