



PERMIT INFORMATION

Permit Number: C-1981-015 Mine Name: Fruita No 1 & 2 Operator: Dorchester Coal Company Operator Address: Greg Lewicki 9054 South Forrest Drive Highlands Ranch, CO 80126	County: Mesa Operation Type: Underground Permit Status: Revoked Ownership: Private
	Operator Representative Present: NA Revoked Mine Site
Operator Representative Signature: (Field Issuance Only) 	

INSPECTION INFORMATION

Inspection Start Date: December 11, 2024 Inspection Start Time: 11:50 Inspection End Date: December 18, 2024 Inspection End Time: 11:52		Inspection Type: Coal Complete Inspection Inspection Reason: Normal I&E Program Weather: Clear	
Joint Inspection Agency: None		Joint Inspection Contacts: None	
Post Inspection Agency: None		Post Inspection Contacts: None	
Inspector(s): Clayton Wein	Inspector's Signature: <i>Clayton Wein</i>		
	Signature Date: 12/30/2024		

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection

N - Roads

N - Availability of Records

N - Reclamation Success

N - Backfill & Grading

N - Revegetation

N - Excess Spoil and Dev. Waste

N - Subsidence

N - Explosives

N - Slides and Other Damage

N - Fish & Wildlife

N - Support Facilities On-site

N - Hydrologic Balance

N - Signs and Markers

N - Gen. Compliance With Mine Plan

N - Support Facilities Not On-site

N - Other

N - Special Categories Of Mining

N - Processing Waste

N - Topsoil

COMMENTS

This report documents the Division's observations taken during a complete inspection of the Fruita No. 1 and 2 Mine, Permit No. C-1981-015. The inspection was conducted on December 18, 2024 by Clayton Wein of the Division. The Fruita No. 1 and 2 Mine is a revoked mine site, therefore no company representative was present for the inspection. The weather was clear with a temperature of 46° F. The ground conditions were mostly dry with some muddy areas.

Access to the Fruita No. 1 and 2 Mine is obtained by following 18 Road to the base of the Bookcliffs. During the inspection 18 Road was closed for repairs and maintenance. The Fruita No. 1 and 2 Mine was not able to be accessed (Photo 1). The Division inspects the mine site quarterly. The Division will conduct a routine monitoring inspection in the first quarter of 2025 once the 18 Road maintenance is complete.

DOCUMENTS RECEIVED: None**OTHER (SPECIFY): None**Number of Partial Inspection this Fiscal Year: 0Number of Complete Inspections this Fiscal Year: 2

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

Number of Partial Inspection this Fiscal Year: 0

Number of Complete Inspections this Fiscal Year: 2

PHOTOGRAPHS



Photo 1: The road closure at 18 Road north of Fruita, CO.

Number of Partial Inspection this Fiscal Year: 0

Number of Complete Inspections this Fiscal Year: 2