

Simmons - DNR, Leigh <leigh.simmons@state.co.us>

C1983059, Terror Creek Loadout, December Inspection Report

Simmons - DNR, Leigh <leigh.simmons@state.co.us> To: Doug Smith <Doug.Smith@oxbow.com>

Mon, Dec 23, 2024 at 8:00 AM

Attached

Leigh Simmons Environmental Protection Specialist



COLORADO

Division of Reclamation,
Mining and Safety

Department of Natural Resources

P 720.220.1180

1313 Sherman Street, Room 215, Denver, CO 80203 leigh.simmons@state.co.us | https://drms.colorado.gov

INSP-REPORTC_C1983059_LDS_12212024022149.pdf 755K



PERMIT INFORMATION

Permit Number: C-1983-059 Mine Name: Terror Creek Loadout Operator: Oxbow Mining, LLC Operator Address: Mr Doug Smith PO Box 535 Paonia, CO 81434	County: Delta Operation Type: Loadout Permit Status: Active Ownership: Private Operator Representative Present: Doug Smith
Operator Representative Signature: (Field Issuance Only)	

INSPECTION INFORMATION

Inspection Start Date: December Inspection Start Time: 02:00 Inspection End Date: Inspection End Time:	17, 2024		Inspection Type: Coal Partial Inspection Inspection Reason: Normal I&E Program Weather: Clear	
Joint Inspection Agency: J		Join	Joint Inspection Contacts:	
None				
Post Inspection Agency:		Post Inspection Contacts:		
None				
Inspector(s):	Inspector's Signature: Signature Date:			
Leigh Simmons	Di		December 23, 2024	

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection N - Roads

N - Availability of Records R - Reclamation Success

N - Backfill & Grading N - Revegetation

N - Excess Spoil and Dev. Waste N - Subsidence

N - Explosives
 N - Slides and Other Damage
 N - Fish & Wildlife
 R - Support Facilities On-site
 N - Hydrologic Balance
 N - Signs and Markers

N - Gen. Compliance With Mine Plan
N - Support Facilities Not On-site
N - Other
N - Special Categories Of Mining

N - Processing Waste N - Topsoil

COMMENTS

This was a partial inspection by Leigh Simmons of the Division of Reclamation, Mining and Safety (Division). The weather was clear and dry. The gate to the site was secure. There was no mining-related activity at the site, but the site was being used for the storage of equipment and materials for other industrial and commercial activities

RECLAMATION SUCCESS - Rule 4.15, Rule 3:

DMEA had removed the power poles from the site.

SUPPORT FACILITIES - Rule 4.04:

The temporary building was empty at the time of the inspection. There had been no recent activity on the lower pad, and the security gate was locked.

Mr Bowden continued to use the shop and the upper pad.

DOCUMENTS RECEIVED

N/A

OTHER (SPECIFY)

N/A

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

Number of <u>Partial</u> Inspection this Fiscal Year: 4 Number of <u>Complete</u> Inspections this Fiscal Year: 2

PHOTOGRAPHS



Figure 1: Power poles removed



Figure 2: West side of lower pad and topsoil stockpile

Number of <u>Partial</u> Inspection this Fiscal Year: 4 Number of <u>Complete</u> Inspections this Fiscal Year: 2