



## Interoffice Memorandum

To: Tri-County Gravel file (M-1977-205)  
From: Rob Zuber *RZ*  
Date: January 23, 2025  
Subject: Materials submitted for resolution of problem from inspection  
(affected area markers)

In the report for the DRMS inspection on October 23, 2024, a problem was cited for insufficient markers for the affected area boundary. In an email dated 21 January 2025, Tyra Bartuska of United Companies sent evidence that 29 new markers were placed around the site, including the areas cited in the October inspection. This evidence included photographs of a subset of the new markers, a table of coordinates for the locations of all 29 new markers, and a map of where the markers were placed. These are included below.



**West side of the portion of permit by the entrance (Site 1371 on the map)**





**Above: Northwest corner of the portion of permit by the entrance (Site 1374 on the map)**

**Below: East side of Pit 3 area (Site 1390 on map)**



**Locations of New Boundary Markers**

<b>Location ID</b>	<b>Latitude</b>	<b>Longitude</b>
1365	38.80277278	-107.6975739
1366	38.80277292	-107.6969711
1367	38.80275222	-107.6989794
1368	38.80275928	-107.6982742
1369	38.80274525	-107.6996342
1370	38.80325158	-107.6998017
1371	38.80357031	-107.6999494
1372	38.80390775	-107.7001656
1373	38.80342889	-107.6998597
1374	38.80487200	-107.7001217
1375	38.80434528	-107.7001467
1376	38.81055797	-107.6971517
1377	38.81088181	-107.6968392
1378	38.81129797	-107.6963906
1379	38.81162833	-107.6960339
1380	38.81187158	-107.6959614
1381	38.81323983	-107.6942358
1382	38.81263036	-107.6956797
1383	38.81237014	-107.6956886
1384	38.81214911	-107.6957628
1385	38.81070697	-107.6901586
1386	38.81055592	-107.6893053
1387	38.81097661	-107.6887503
1388	38.81095533	-107.6906811
1389	38.81131183	-107.6883094
1390	38.81172764	-107.6877597
1391	38.81209333	-107.6872778
1392	38.81237994	-107.6869031
1393	38.81039928	-107.6895119



