

Minerals Annual Report

Permit Boundary

Currently Affected (8)

Newly Affected (9)

Reclaim (10)

Affected (11)

Reclaimed 2020 (12)


Stockpile Top Soil

MARTIN PIT 1-A

FILE NO. M-1990-140 DURAN & PEARCE CONTRACTORS

EXHIBIT 'C-2'

S1/2 NW1/4 OF SECTION 13, TEN R91W, 6th P.M., MOFFAT COUNTY, COLORADO



NOTES

1. THERE IS A 200 FOOT NO MINING BUFFER ADJACENT TO THE OVERHEAD POWER LINES ON THE SOUTH BOUNDARY.
2. THERE IS A 200 FOOT NO MINING BUFFER ADJACENT TO THE OVERHEAD POWER LINE ON THE EAST BOUNDARY.
3. THERE IS A 20 FOOT NO MINING BUFFER ADJACENT TO THE NORTH AND WEST PROPERTY LINES.
4. THE FENCES ALONG THE EAST, WEST, AND SOUTH BOUNDARIES ARE COMMON FENCES.
5. THERE ARE NO STRUCTURES OF VALUE WITHIN 200 FEET OF THE PROPERTY BOUNDARIES, OTHER THAN THOSE SHOWN.

Gordon R. Downing
Colorado PLS #20090

DURAN & PEARCE CONTRACTORS	MARTIN PIT 1-A EXHIBIT 'C-2'
FILE NO. M-1990-140	
NOTED BY LAND SURVEYOR MOFFAT COUNTY, COLORADO	DATE: 1/14/2024 TIME: 1:14 PM BY: GORDON R. DOWNING FAX: 278-5613

NOTICE: ACCORDING TO COLORADO LAW, YOU MUST COMMENCE ANY LEGAL ACTION BASED ON ANY DEFECT IN THIS SURVEY WITHIN TWO YEARS FROM THE DATE OF CERTIFICATION SHOWN HEREON.