



STATE OF
COLORADO

Reilley - DNR, Robin <robin.reilley@state.co.us>

inspection reports Feb 2025 Seneca IIW and WF Mines

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Thu, Feb 27, 2025 at 10:58 AM

To: "Kawcak, Miranda" <MKawcak@peabodyenergy.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Morning Miranda,

Please find the above mentioned inspection reports. The inspections comprised partial inspections.

Thank you

Robin Reilley, M.S. GISP
Environmental Protection Specialist II

image.png

P [303.866.3567](tel:303.866.3567) |

F [303.832.8106](tel:303.832.8106)

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203

Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | <http://mining.state.co.us>

2 attachments

Ins_Partial_2025_02Feb.pdf
371K

Insp_Partial_WilliamsFork_2025_02_Feb.pdf
357K



COLORADO
 Division of Reclamation,
 Mining and Safety
 Department of Natural Resources

25 February 2025

PERMIT INFORMATION

Permit Number: C-1981-044 Mine Name: Williams Fork Mines Operator: Moffat County Mining, LLC Operator Address: Ms. Miranda Kawcak 29515 Routt County Road #27 Oak Creek, CO 80467	County: Moffat Operation Type: Underground Permit Status: Active Ownership: Private None as the site was inaccessible at this time of year.
This report was issued electronically from the Divisions' Denver Office.	

INSPECTION INFORMATION

Inspection Start Date: 25 February 2025 Inspection Start Time: 12:00 a.m. Inspection End Date: 25 February 2025 Inspection End Time: 12:15 p.m.	Inspection Type: Partial Inspection Inspection Reason: Normal I&E Program Weather: Clear
Joint Inspection Agency: None	Joint Inspection Contacts: No
Post Inspection Agency: None	Post Inspection Contacts: No
Inspector(s): Robin Reilley, M.S. GISP Hunter Ridley	Inspector's Signature:  Signature Date: 27 February 2025

Number of Partial Inspection this Fiscal Year: 4

Number of Complete Inspections this Fiscal Year: 3

Inspection Topic Summary	
NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable	
N - Air Resource Protection	R - Roads
N - Availability of Records	N - Reclamation Success
N - Backfill & Grading	N - Revegetation
NA - Excess Spoil and Dev. Waste	N - Subsidence
NA - Explosives	N - Slides and Other Damage
N - Fish & Wildlife	N - Support Facilities On-site
N - Hydrologic Balance	N - Signs and Markers
N - Gen. Compliance With Mine Plan	N A - Support Facilities Not On-site
NA - Other	NA - Special Categories Of Mining
NA - Processing Waste	N - Topsoil

COMMENTS

This was partial inspection conducted aurally of the Williams Fork Mine; permit C1981044, operated by Moffat County Mining LLC. The image was collected by Hunter Ridley, and the report prepared by me, Robin Reilly of the DRMS. No mine representative was present during the inspection. The sky was clear.

INSPECTION

GENERAL MINE PLAN COMPLIANCE:

SIGNS and MARKERS – Rule 4.02

- The mine identification sign was in place at the site entrance from Highway 13. The sign was intact, displaying all required information: mine name, operator name, address, phone number, DRMS permit number and contact information.

ROADS – Rule 4.03

Construction 4.03.1(3) I 4.03.2(3); Drainage 4.03.1(4) I 4.03.2(4); Surfacing and Maintenance 4.03.1(5) and (6) I 4.03.2(5) and (6); Reclamation 4.03.1(7) I 4.03.2(7)

- Main haul roads were snow covered.
- The site was not accessible due to winter conditions and the roads into the site are not plowed.

DOCUMENTS RECEIVED

None

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

Number of Partial Inspection this Fiscal Year: 4

Number of Complete Inspections this Fiscal Year: 3

PHOTOGRAPHS



***Photo 1:** Williams Fork mine identification sign at the entrance from Highway 13.*

Number of Partial Inspection this Fiscal Year: 4

Number of Complete Inspections this Fiscal Year: 3