



**GOLD CANYON
PARTNERS, LLC**

GOLD CANYON PARTNERS, LLC

1602 W Placita Sin Nieve

Sahuarita, AZ 85629

Tel.: +1 (520) 465-8650

E-mail: Rodney.Blakestad@gmail.com

September 3, 2024

Note to reader: This document was prepared September 3, 2024, but I have no record that it was updated with the 40-acre site locations. Immediate review and completion of the abandonment report will be undertaken, if it was not previously completed by a third party. Prepared by Rodney A. Blakestad, April 21, 2025.

RE: Report on abandonment of three exploration drill holes
REX Project, Montrose County
File No. P-2022-019 (MD01)

Division of Reclamation, Mining and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

Dear Director,

During July and August 2023, Sunrise Minerals Inc. conducted minerals exploration drilling activities in Montrose County under permit number P-2022-019, Prospecting Modification MD-01. The exploration project included making improvements of an existing access road to the area of drilling activity, construction of short trails (<100 ft) to three drill sites, drilling of three diamond core exploration drill holes, and subsequent plugging of the holes and reclamation of the drill sites. The report is provided to fulfill the requirement under CCR, Rule 2 CCR 407-4, 5 Exploration Operations, for a report on those activities.

Road improvements, drill site construction and drilling activities were carried out on behalf of Sunrise Minerals Inc. under the oversight of Rodney A. Blakestad, J.D., C.P.G., site manager. The field work was performed between June 27 to August 29, 2023. Reclamation of the drill sites ran, in-part, concurrently with drilling activities, with a final site reclamation and initial reseeding completed August 28, 2023. A field review of the initial reclamation activities was conducted July 1 to July 3, 2024, which included upgrade of stormwater controls and additional seeding of the BLM approved seed mix (BLM West End Seed Mix).

Completion date of the abandonment of the drill sites was August 29, 2024. Several additional site reviews will occur during 2024 to assess re-seeding growth progress, and as may be directed by DRMS and BLM.

Neither artesian water nor ground water were encountered in any of the three drill holes. The location of the drill holes, by average of numerous hand-held readings, are as follows:

	UTM Datum NAD-83, Zone 12	Depth (ft)	Angle
REX-01	698924E 4246332.5N	270	-90
REX-02	698889E 4246300.5N	335	-90
REX-03	698975E 4246316.5N	150	-90

Rodney A. Blakestad, Managing Partner
Gold Canyon Partners, LLC