



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

April 29, 2025

Kacey Campbell
Sedgwick County Road and Bridge
223 S Cedar St
Julesburg, CO 80737

Re: Skold Pit, Permit No. M-1998-032, Problem Abated

Dear Mr. Campbell:

On April 29, 2025, the Division of Reclamation Mining and Safety (Division) received your corrective action documentation for the following problems identified in the Division's March 25, 2025 inspection report:

INSPECTION TOPIC: Signs & Markers

PROBLEM: The affected area boundary markers are missing or incorrectly placed. This is a problem for failure to maintain boundary markers around the affected area as required by Section 3.1.12(2) of the rule.

CORRECTIVE ACTIONS: The operator shall conduct a survey and replace the boundary markers in the correct location(s). The operator shall provide the boundary marker coordinates and photographic proof to the Division that this has been done by the corrective action date.

CORRECTIVE ACTION STATUS: Abated. The permit boundary markers were identified and clarified to be the cement blocks on site. Coordinates of these markers were provided as well.

If you require additional information, or have questions or concerns, please feel free to contact me by phone at (720) 812-2002, or by email at joel.renfro@state.co.us.

Sincerely,

Joel Renfro
Environmental Protection Specialist

Cc: Amy Eschberger, DRMS

