

STATE OF
COLORADO

Gibson - DNR, Amber <amber.gibson@state.co.us>

Inspection Report, Mesa DeMaya Pit

Gibson - DNR, Amber <amber.gibson@state.co.us>

Mon, May 5, 2025 at 8:26 AM

To: Brian Heguy <brian.heguy@lasanimascounty.org>

Hi Brian,

The following is the inspection problem cited in the Division's inspection report of the inspection conducted on March 26, 2025:

INSPECTION TOPIC: Signs & Markers**PROBLEM:** The affected area boundary markers are missing or incorrectly placed. This is a problem for failure to maintain boundary markers around the affected area as required by Section 3.1.12(2) of the rule.**CORRECTIVE ACTIONS:** The Operator shall replace the boundary markers in the correct location(s). The Operator shall provide proof to the Division that this has been done by the corrective action date.

Per your request, the Division approves an extension to the corrective action date. The corrective action date for this inspection problem is now set for **May 30, 2025.**

Thank you,

Amber Michels Gibson
Environmental Protection Specialist I



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P 720.836.0967 | F 303.832.8106 |
amber.gibson@state.co.us

Mailing: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

Physical: 1313 Sherman Street, Room 215, Denver, CO 80203

<https://drms.colorado.gov/>

[Quoted text hidden]