



MINERAL PROSPECTING DRILL HOLE
PERMANENT ABANDONMENT FINAL REPORT

Pursuant to the terms of 34-32-113(5.5)(d) and (e) of the Act and Rule 5.7 of the Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for Hard Rock, Metal, and Designated Mining Operations, abandonment reports shall be submitted to the Division within 60 days of abandonment for any drill hole with artesian flow, or within 12 months of abandonment for any other drill hole.

	P
(PROSPECT SITE NAME)	(PROSPECT NOI No.)

I. DRILL HOLE: Drill Hole I.D. No.

For this Section I, please attach completed drill hole logs **OR** complete the following information:

(Total Depth)	(Depth of Unconsolidated Material)	(Depth of Penetration into Bedrock)

Was water encountered: No ☐ Yes ☐ if so, at what depth(s):

Was water encountered in either Volcanic or Sedimentary Rock: No ☐ Yes ☐

Date Drilled: Date Permanently Abandoned:

II. OPERATOR (PROSPECTOR) :

DRILLER:

(Name)		(Name)	
(Address)		(Address)	
(City)	(State)	(City)	(State)
(Zip)	() (Telephone No.)	(Zip)	() (Telephone No.)

III. LOCATION:

The following information is required for ALL prospecting drill holes:



1/4 of the 1/4 of Section Township Range

Principal Meridian County

If the area has not been surveyed, supply the Longitude West and Latitude North,
or attach a location map, preferably a USGS Quad.

The following additional information is required for artesian flowing holes:

Feet North South from the South North section line

feet east West from the west East section line

NOTE: In the case of closely spaced drill holes having similar geologic and hydrologic characteristics, the Operator may, with the approval of the Division, submit a single consolidated final report including the location of all drill holes and a description of abandonment technique. In such case, complete one abandonment final report form and attach a list of drill hole locations. If more space is needed to provide any of the information for this form, please attach separate sheets.

IV. Complete Either Subsection A or B:

PERMANENT ABANDONMENT (Check either box 1 or subsection 2 boxes as appropriate and provide the requested information)

☐ 1. Plugged dry hole, method of plugging:

Depth at which concrete plug set: feet below ground surface.

☐ 2. Sealed Hole (when groundwater is encountered):

☐ 2a. Neat Cement Grout, top to bottom: grout mixture used:

Intervals grouted (feet beneath ground surface, method and materials):

☐ 2b. Neat Cement Grout, interval grouting: grout mixture used:

Intervals grouted (feet beneath ground surface, method and materials):

☐ 2c. Abandonment Fluid Mixture (Such as Sodium Bentonite with Polymer) Brand Name:

Marsh Funnel viscosity of abandonment fluid: sec.

Type of surface plugging used:

Depth at which plug set:

feet below ground surface,

Method:

- ☐ 2d. Other method used with approval of the Division of Reclamation, Mining and Safety; describe in detail method and materials used on a separate attached sheet.

B. CONVERSION TO A WATER WELL

State Engineer's Permit No.:

(attach copy of permit)

County Where Well is Located:


Water Well Use:

V. METHOD OF RECLAIMING DRILL SITE SURFACE DISTURBANCE:

The Operator who conducted the prospecting drill operation states that the information set forth hereupon is true to the best of their knowledge.

(Name of Operator's Representative)

(Title)



Operator's Representative)

30 May 2024

(Date)

24WBRA DH Abandon Groundhog P2021-008

Colorado Division of Reclamation Mining and Safety

MINERAL PROSPECTING DRILL HOLE PERMANENT ABANDONMENT FINAL REPORT

Prospect Number	Prospect Site Name	Project Area	DH ID	Total Depth (ft)	Depth of unconsolidated material	Depth of Penetration into bedrock	Was water encountered?	Was water encountered in either volcanic or sedimentary rock?	Date Drilled	Date Permanently Abandoned
P-2021-008	Wedding Bell Mountain	Ground Hog	24WBRA001	340	2	338	No	No	2 Nov 2024	16 Nov 2022
P-2021-008	Wedding Bell Mountain	Ground Hog	24WBRA002	340	2	338	No	No	2 Nov 2024	16Nov 2022
P-2021-008	Wedding Bell Mountain	Ground Hog	24WBRA003	340	2	338	No	No	4 Nov 2024	16 Nov 2022
P-2021-008	Wedding Bell Mountain	Ground Hog	24WBRA004	340	2	338	No	No	6 Nov 2024	16 Nov 2022
P-2021-008	Wedding Bell Mountain	Ground Hog	24WBRA005	335	2	333	No	No	5 Nov 2024	17 Nov 2022
P-2021-008	Wedding Bell Mountain	Ground Hog	24WBRA006	340	2	338	No	No	8 Nov 2024	19 Nov 2022
P-2021-008	Wedding Bell Mountain	Ground Hog	24WBRA007	380	2	378	No	No	8 Nov 2024	20 Nov 2022
P-2021-008	Wedding Bell Mountain	Ground Hog	24WBRA008	370	2	368	No	No	10 Nov 2024	20 Nov 2022
P-2021-008	Wedding Bell Mountain	Ground Hog	24WBRA009	440	2	438	No	No	10 Nov 2024	20 Nov 2022

24WBRA DH Abandon Groundhog P2021-008

Operator	Driller	¼ ¼ Sec T R Meridian	County	Easting (WGS84 UTM Zn12)	Northing	Elevation (ft)	Latitude WGS84	Longitude	Elevation (ft)
Thor Energy PLC/Standard Minerals, Inc. c/o Wolcott LLC 739 Bookcliff Ave Grand Junction, CO 81501	Envirotech Drilling LLC 900 E. 4 th Street Winnemucca, NV 89445 775.623.2339	NE¼ NE1/4 Sec 21 T45N R18W NMPM	San Miguel	688092	4223970	6860	38.144010	-108.853573	6860
Thor Energy PLC/Standard Minerals, Inc. c/o Wolcott LLC 739 Bookcliff Ave Grand Junction, CO 81501	Envirotech Drilling LLC 900 E. 4 th Street Winnemucca, NV 89445 775.623.2339	NE¼ NE1/4 Sec 21 T45N R18W NMPM	San Miguel	688093	4223969	6860	38.144010	-108.853573	6860
Thor Energy PLC/Standard Minerals, Inc. c/o Wolcott LLC 739 Bookcliff Ave Grand Junction, CO 81501	Envirotech Drilling LLC 900 E. 4 th Street Winnemucca, NV 89445 775.623.2339	NE¼ NE1/4 Sec 21 T45N R18W NMPM	San Miguel	688092	4223968	6860	38.144010	-108.853573	6860
Thor Energy PLC/Standard Minerals, Inc. c/o Wolcott LLC 739 Bookcliff Ave Grand Junction, CO 81501	Envirotech Drilling LLC 900 E. 4 th Street Winnemucca, NV 89445 775.623.2339	NE¼ NE1/4 Sec 21 T45N R18W NMPM	San Miguel	688091	4223969	6860	38.144010	-108.853573	6860
Thor Energy PLC/Standard Minerals, Inc. c/o Wolcott LLC 739 Bookcliff Ave Grand Junction, CO 81501	Envirotech Drilling LLC 900 E. 4 th Street Winnemucca, NV 89445 775.623.2339	NE¼ NE1/4 Sec 21 T45N R18W NMPM	San Miguel	688144	4224065	6850	38.144854	-108.852955	6850
Thor Energy PLC/Standard Minerals, Inc. c/o Wolcott LLC 739 Bookcliff Ave Grand Junction, CO 81501	Envirotech Drilling LLC 900 E. 4 th Street Winnemucca, NV 89445 775.623.2339	NE¼ NE1/4 Sec 21 T45N R18W NMPM	San Miguel	688128	4224077	6860	38.144696	-108.853142	6860
Thor Energy PLC/Standard Minerals, Inc. c/o Wolcott LLC 739 Bookcliff Ave Grand Junction, CO 81501	Envirotech Drilling LLC 900 E. 4 th Street Winnemucca, NV 89445 775.623.2339	NE¼ NE1/4 Sec 21 T45N R18W NMPM	San Miguel	688092	4223969	6860	38.144001	-108.853573	6859
Thor Energy PLC/Standard Minerals, Inc. c/o Wolcott LLC 739 Bookcliff Ave Grand Junction, CO 81501	Envirotech Drilling LLC 900 E. 4 th Street Winnemucca, NV 89445 775.623.2339	NE¼ NW1/4 Sec 22 T45N R18W NMPM	San Miguel	688135	4224093	6860	38.145108	-108.853050	6859
Thor Energy PLC/Standard Minerals, Inc. c/o Wolcott LLC 739 Bookcliff Ave Grand Junction, CO 81501	Envirotech Drilling LLC 900 E. 4 th Street Winnemucca, NV 89445 775.623.2339	NE¼ NE1/4 Sec 21 T45N R18W NMPM	San Miguel	688117	4224206	6940	38.146130	-108.853225	6940

Hole Plugging Method	Method of Reclaiming drill site surface disturbance	Notes
No casing, surface or otherwise was left in the hole. The hole backfilled with dry cuttings or if wet cuttings, the sump was pumped back into the hole to within 5 feet of the surface, then a spider-type plug was placed and then backfilled to the surface with high-quality bentonite chips.	If present, a sump was backfilled and then the pad regraded to approximate natural surface before disturbance, reserved topsoil respread, then seeded with an approved mix and then raked/harrowed to cover seeds	
No casing, surface or otherwise was left in the hole. The hole backfilled with dry cuttings or if wet cuttings, the sump was pumped back into the hole to within 5 feet of the surface, then a spider-type plug was placed and then backfilled to the surface with high-quality bentonite chips.	If present, a sump was backfilled and then the pad regraded to approximate natural surface before disturbance, reserved topsoil respread, then seeded with an approved mix and then raked/harrowed to cover seeds	
No casing, surface or otherwise was left in the hole. The hole backfilled with dry cuttings or if wet cuttings, the sump was pumped back into the hole to within 5 feet of the surface, then a spider-type plug was placed and then backfilled to the surface with high-quality bentonite chips.	If present, a sump was backfilled and then the pad regraded to approximate natural surface before disturbance, reserved topsoil respread, then seeded with an approved mix and then raked/harrowed to cover seeds	
No casing, surface or otherwise was left in the hole. The hole backfilled with dry cuttings or if wet cuttings, the sump was pumped back into the hole to within 5 feet of the surface, then a spider-type plug was placed and then backfilled to the surface with high-quality bentonite chips.	If present, a sump was backfilled and then the pad regraded to approximate natural surface before disturbance, reserved topsoil respread, then seeded with an approved mix and then raked/harrowed to cover seeds	
No casing, surface or otherwise was left in the hole. The hole backfilled with dry cuttings or if wet cuttings, the sump was pumped back into the hole to within 5 feet of the surface, then a spider-type plug was placed and then backfilled to the surface with high-quality bentonite chips.	If present, a sump was backfilled and then the pad regraded to approximate natural surface before disturbance, reserved topsoil respread, then seeded with an approved mix and then raked/harrowed to cover seeds	
No casing, surface or otherwise was left in the hole. The hole backfilled with dry cuttings or if wet cuttings, the sump was pumped back into the hole to within 5 feet of the surface, then a spider-type plug was placed and then backfilled to the surface with high-quality bentonite chips.	If present, a sump was backfilled and then the pad regraded to approximate natural surface before disturbance, reserved topsoil respread, then seeded with an approved mix and then raked/harrowed to cover seeds	
No casing, surface or otherwise was left in the hole. The hole backfilled with dry cuttings or if wet cuttings, the sump was pumped back into the hole to within 5 feet of the surface, then a spider-type plug was placed and then backfilled to the surface with high-quality bentonite chips.	If present, a sump was backfilled and then the pad regraded to approximate natural surface before disturbance, reserved topsoil respread, then seeded with an approved mix and then raked/harrowed to cover seeds	
No casing, surface or otherwise was left in the hole. The hole backfilled with dry cuttings or if wet cuttings, the sump was pumped back into the hole to within 5 feet of the surface, then a spider-type plug was placed and then backfilled to the surface with high-quality bentonite chips.	If present, a sump was backfilled and then the pad regraded to approximate natural surface before disturbance, reserved topsoil respread, then seeded with an approved mix and then raked/harrowed to cover seeds	
No casing, surface or otherwise was left in the hole. The hole backfilled with dry cuttings or if wet cuttings, the sump was pumped back into the hole to within 5 feet of the surface, then a spider-type plug was placed and then backfilled to the surface with high-quality bentonite chips.	If present, a sump was backfilled and then the pad regraded to approximate natural surface before disturbance, reserved topsoil respread, then seeded with an approved mix and then raked/harrowed to cover seeds	