



STATE OF
COLORADO

Reilley - DNR, Robin <robin.reilley@state.co.us>

Review 2025 Q1 DMRs

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Wed, May 7, 2025 at 11:24 AM

To: Graham Roberts <graham.roberts@trappermine.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Dear Ms. Roberts

Thank you for the timely submission of Trapper's February, March and 2025 Q1 DMR's. Please find The Division's review of the submitted reports attached. Thank you for the additional information pertinent to the February DMR's. The Division has no concerns at this time.

Kind Regards

Robin Reilley, M.S. GISP
Environmental Protection Specialist II

image.png

P 303.866.3567 |

F 303.832.8106

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203

Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | <http://mining.state.co.us>

2 attachments



Review_DMR_2025_3March_Trapper.pdf

179K



Review_DMR_2025_2Feb_Trapper.pdf

181K



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

Graham Roberts
Trapper Mining Inc.
P.O. Box 187
Craig, CO 81626

7 May 2025

Re: Trapper Mine (Permit No. C1981-010)
Review of DMR's 2025 February

Dear Mr. Roberts:

The Division has received and reviewed the 2025 February Discharge Monitoring Reports (DMRs), including the acute WET testing results for the Trapper Mine. The DMRs were received electronically by the Division on 27 March 2025. Thank you for your timely submittal of this information. Trapper submits DMRs to the Division, in accordance with Rule 4.05.13(2)(a)(iii).

Trapper reported the following outfalls discharged during the month:

- Johnson #10 NPDES 001
- No Name Pond #5 NPDES 002
- East Pyeatt #2 NPDES 011
- Middle Flume #20 NPDES 20
- East Middle Flume #21 NPDES 21

Trapper reported that iron was exceeded and included their letter addressed to CDPHE regarding the excursion in the submission of their February DMRS to DRMS. Also, referenced was NOAA temperature information for the period in question. Exceedances appear to be a result of warming temperatures in early February and associated rapid snowmelt. None of the outfalls requiring acute WET testing discharged.

The Division does not have any questions, concerns, or further comments at this time. If you have any questions or need additional information, please contact me.

Sincerely,

Robin Reilley, M.S. GISP
Environmental Protection Specialist II



Robin.reilley@state.co.us