

STATE OF
COLORADO

Reilley - DNR, Robin <robin.reilley@state.co.us>

Review 2025 Q1 Yoast and Seneca IIW compliance reports

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Thu, May 15, 2025 at 3:36 PM

To: "Kawcak, Miranda" <MKawcak@peabodyenergy.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Dear Ms. Kawcak,

Thank you for the timely submission of Seneca Properties 2025 Q1 compliance reports. Please find The Division's review of the submitted reports attached.

DRMS noted no sampling took place at pond 17. Let me know if I overlookd that sampling occured.

If you have concerns or questions please let me know.

Robin Reilley, M.S. GISP
Environmental Protection Specialist II

image.png

P [303.866.3567](tel:303.866.3567) |F [303.832.8106](tel:303.832.8106)

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203

Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | <http://mining.state.co.us>

4 attachments**Review_Ponds_2025_Q1_Yoast.pdf**

222K

**Review_DMR_Yoast82_2025_Q1.pdf**

191K

**Review_DMR_Seneca57_2025_Q1.pdf**

198K

**Review_Ponds_2025_Q1_Seneca57.pdf**

235K



15 May 2025

Miranda Kawcak
Environmental Manger
Peabody, Colorado Operations

Re: Seneca II West (Permit No. C1982057)
Review Impoundment Report 2025 Q1

Dear Ms. Kawcak:

Thank you for your timely submittal of the 2025 quarter one pond reports for the Seneca IIW Mine. The Colorado Division of Reclamation, Mining and Safety (The Division) received the above referenced reports on 12 May 2025. Sediment pond inspections were conducted by Jason Herden of Seneca Coal Company on 25 March 2025. The report complies with the applicable sections of Rule 4.05.9.

Ponds were holding water and snow covered at the time of inspection. The following ponds were discharging at the time of inspection:

<i>Pond</i>	<i>Gallons per Minute (gpm)</i>
006	52.3
016	37.8
017	3.9

Sediment levels appeared acceptable, and no maintenance items were identified.

The following structures have achieved bond release:

- Ponds 005, 009,
- Stock Tanks T-1, T-5, T-18, T-20, T-22, T-24, T-25, T-26 and T-27

Monitoring items comprise a known slump at Pond 006, a spring near the Pond 005 dam, and an occasional seep at Pond 016. DRMS understands that Seneca Coal Company monitors these items on a regular basis.

Sincerely,

Robin Reilley, M.S. GISP
Environmental Protection Specialist II
Robin.reilley@state.co.us

