



STATE OF
COLORADO

Jesse - DNR, Todd <todd.jesse@state.co.us>

Q1 Report Reviews

1 message

Jesse - DNR, Todd <todd.jesse@state.co.us>
To: Kurt Blunt <kblunt@deserado.com>

Wed, Jul 2, 2025 at 11:36 AM

Kurt,

Please see the atted review letters from the Q1 Pond & Subsidence Report, DMR Report, and Wastebank Report.

Thanks,
Todd

--

Environmental Protection Specialist
Minerals Program, Grand Junction Field Office
Colorado Division of Reclamation Mining and Safety
720-688-0626

3 attachments



2025-07-02 1st Quarter 2025 DMRs Review Letter C-1981-018.pdf
164K



2025-07-02 1st Quarter Pond Inspection Report and Subsidence Monitoring Report Review Letter C-1981-018.pdf
202K



2025-05-07 1st Quarter Coal Waste Bank Report Review Letter C-1981-018.pdf
170K



7/2/2025

Kurt Blunt
Blue Mountain Energy, Inc.
3607 County Rd. 65
Rangely, CO 81648

**RE: Deserado Mine, Permit No. C-1981-018
1st Quarter 2025 Professional Certification for the Coal Processing Waste
Banks**

Dear Kurt,

The Division of Reclamation, Mining and Safety (the Division) has reviewed the Professional Certification for the Coal Processing Waste Banks for the 1st quarter of 2025. The report was received on April 28, 2025. The Division finds the report to be in compliance with the following Rules:

- 4.10.2(1)** – The coal waste banks were inspected, on behalf of the person conducting surface coal mining operations, by a qualified registered engineer.
- 4.10.2(2)(a)** – The inspection was conducted quarterly as required by the Division.
- 4.10.2(2)(b)** – The inspection included observations necessary to evaluate the potential hazard to human life and property, to ensure that all organic material and topsoil have been removed and that proper construction and maintenance are occurring in accordance with the plan submitted under Rule 2.05.3(8) and approved by the Division.
- 4.10.2(2)(c)** – The engineer considered the steepness of the slopes, seepage, and other visual factors which would indicate potential failure, and the results of failure with respect to the threat to human life and property.
- 4.10.2(2)(d)** – Copies of the inspection findings are maintained at the mine site.
- 4.10.2(3)** – There were no potential hazards identified in the 1st Quarter Professional Certification for the Coal Processing Waste Banks.
- 4.10.2(4)(c)** – Compaction testing was conducted roughly every thirty days during the quarter on newly compacted areas.



5/5/2025

4th Quarter Coal Waste Bank Report Review

Refuse material was hauled and placed at the RP-A, RP-5A, and RP-2/3/4 refuse piles during the quarter. There were no indications of seepage or any indications of slope failure. The slopes of the piles are stable and only some localized erosion has occurred. The surface drainage facilities are properly conveying surface runoff from the refuse bank areas.

This concludes the Division's review of the 1st quarter 2025 Professional Certification of the Coal Processing Waste Banks for the Deserado Mine. If you have any questions, please contact me at (720) 688-0626 or todd.jesse@state.co.us.

Sincerely,

A handwritten signature in blue ink that reads "Todd Jesse".

Todd Jesse
Environmental Protection Specialist
todd.jesse@state.co.us

cc: Clayton Wein, Environmental Protection Specialist
Travis Marshall, Senior Environmental Protection Specialist GJFO