



COLORADO

Division of Reclamation,
Mining and Safety

Department of Natural Resources

July 30, 2025

Jason McGraw
General Shale Brick, Inc.
1845 W Dartmouth Ave
Denver, CO 80110

Re: Dawson Mine, Permit No. M-1977-392, Sediment Control Problem Abated

Dear Mr. McGraw:

On July 29, 2025 the Division of Reclamation Mining and Safety (Division) received your corrective action documentation for the following problems identified in the Division's March 5, 2025 inspection report:

INSPECTION TOPIC: Sediment Control

PROBLEM #1: Erosion rills and gullies were observed throughout the portion of the permit area that lies south of the access road, including a significant erosion feature that's present on the southern highwall of the East Pit. This is a problem at this time for failure to protect the affected land from erosion pursuant to C.R.S. 34-32.5-116(4)(j) and Rule 3.1.6(3).

CORRECTIVE ACTIONS: The operator shall provide photo documentation to the Division verifying erosion gullies and ruts have been repaired, and that the site has have been reconstructed and stabilized to prevent erosion damage by the corrective action date.

CORRECTIVE ACTION STATUS: Abated. The operator provided documentation that the erosion rills and gullies were repaired on July 29, 2025.

If you require additional information, or have questions or concerns, please feel free to contact me by phone at (720) 793-3031, or by email at ursula.armstrong@state.co.us.

Ursula Armstrong
Environmental Protection Specialist

Cc:
Amy Eschberger, DRMS

