Schwartzwalder Daily Summary Report



Report Date: 8/8/2025		Lead O	perator:	Chris P			
		Assistant C)porator(s):	Patrick D			
		Assistant Operator(s):			Bryant A		
Effluent Discharged: 0.708 Mgal			MW-18	B Level:	204.2 ft	86.9 ft	
Average	Flowrate:	168.9 gpm	Transduc	cer Level:	219.5 ft	76.5 ft	
Effluent	to Date:	11.999 Mgal	(Field Reading Value below 150')				
	рН		Flowrate				
9.5			250				
9			200				
8.5							
8			150				
7.5			100				
6.5			50				
6							
5.5	00 0:00 12:0	00 0:00 12:00 0:00	0:00 12:0	0 0:00 12:0	0 0:00 1	12:00 0:00	
0:00 12:0	0:00 12:0	0:00 12:00 0:00	Finished Water Quality				
	Complianc	e Level	 Parameters			Cond	
0 (ff)	•		Values	Temp 21°C	pH 7.81	180 µS/cm	
20 <u>e</u>			values	210	7.01	100 μο/επ	
± 40			Chemical Inventory				
060			Chemicals	Antiscalant	NaOH	BaCl	
Depth below 150' Steve Level (ff) 0			Vol. Used	11 Gal	58 Gal	5 Gal	
100			Vol. Remaining	211 Gal	222 Gal	50 Gal	
3-Apr	23-May	12-Jul 31-Aug	Vol. Staged	460 Gal	135 Gal	50 Gal	
<u> </u>	─ Transducer Leve	MW-18	Days Available	61 Days	6 Days	20 Days	


Safety Issues/Concerns:


- N/A

Notes:


- Performed high pH CIP on RO#1. Flushed RO and brought 2 ROs online at around 9:40 AM on 8/8/25.
- Samples Outfall 001A TSS
- Batch 30 gal of BaCl
- Onsite Monthly meeting with Peter Hays.
- A suspected power issue occurred onsite on 8/10 at around 13:30. Plant was still running however there were issues with the Antiscalant and BaCl pump not operatoring. The plant was remotely shutdown at around 16:06 since chemical dosing was unable to be confirmed.

NOTE: The level graph has been adjusted to show field readings relative to the water level below the compliance elevation (150' below the Steve Adit - 6459' ASL). Data from 5/1/2025 to 6/5/2025 was recorded using an atmospheric transducer with a 500-ft cable, installed at the end of the 2024 season and remained in place over the winter. On 6/6/2025, it was replaced with an absolute transducer with a 600-ft cable at a lower depth. A 77.1-ft difference in readings was observed. While some of offset may be a result from the deeper installation and transducer type, the old data's accuracy is questionable due to damage to the atmospheric vent, which may have allowed moisture intrusion.





dustrial Water Controlle



R

Influent ORP(S1)	0 mV	NWA		Mormal			
Time Circ Carl							

Model Number: wind84-14bmn Controller Serial 1704130666 Number: Core Serial 1704130666 Number:

Outputs	Output Status				
RO Shut Off(R6)	Off Sensor Error				

4-20 mA Outputs Output Status	Output Process Value	Output ma Value	
Anti-Scale Pump 0.00% 0.00% .		4.00	
Anti-Scale Pump 0.00% 0.00%	MA	4.00	
Barium Chloride Pump(AO4) 0.00%		4.00	

4-20mA Imputs	Measure	Last O Hrs				
		AVG		MAK	Status	Total
RO#2 Feed Pressure(AI_2)	INWALID psi	INVALID	INVALID		Sensor Error	MA
RO#1 Feed Pressure(AI_4)	INVALID Psi	INVALID	INVALID	INVALID		M/A
Anti-Scale Tank(AI_5)	INVALID gal.	INVALID	INVALID		Latian en Louis Indiana I annon	N/A
RO Feed Flow(AI_6)	0.00 gal/min	0.00	0.00	0.00		0.00
Mine Pool(AI_7)	INVALID ft	INWALID	INVALID:	INVALID	eelingii galaa ja j	gal N/A
Concentrate Line(AI_S)	INVALID Psi	INWALID	INVALID			
Digital Impate 14.						

Alarm Status

- 1) RO#2 Feed Pressure (AI_2)Sensor Error 2)RO#1 Feed Pressure (AI_4)Sensor Error
 - 3)Anti-Scale Tank (AI_5)Sensor Error
- 4)RO Feed Flow (Al_6)Sensor Error 5)Mine Pool (AL 7)Sensor Error
- 6)Concentrate Line (ALD)Sensor Error

Input Typestatus! Floor Sump Alarm (DI_1) Interlock Open

> © 1999 - 2014 Walchem An Iwaki America Incorporated Company Five Boymton Rd Holliston ALA

Powered By: Virtual Achiel Bellen

QuickPanel

PRO 100 RO #2

RO MACHINE

STOP



THE E-STOP BUTTON HAS BEEN PRESSED. POWER IS NOT FLOWING TO THE INPUT/OUTPUT CARDS. PULLING OUT THE E-STOP AND PRESSING THE SYSTEM RESET BUTTON WILL RETURN THE SYSTEM TO NORMAL.

SCREEN SELECT



GE Osmonics



ALARM RESET

GE Fanuc

QuickPanel View