



STATE OF
COLORADO

Girardi - DNR, Chris <chris.girardi@state.co.us>

King Pit M1987012- Approval of Extension for Corrective Actions

1 message

Girardi - DNR, Chris <chris.girardi@state.co.us>

Fri, Aug 29, 2025 at 2:05 PM

To: Paul Bottini <paul@southwayco.com>

Cc: PFM Consulting <pfmconsultingcompany@gmail.com>, Jared Ebert - DNR <jared.ebert@state.co.us>

Good afternoon,

Attached to this email is a pdf from the Division granting an extension to conduct and document corrective actions at the King Pit, permit number M1987012.

A hard copy will not be sent unless requested. Please feel free to reach out if you have any questions.

Have a great weekend,

Chris Girardi

Environmental Protection Specialist



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P: (720) 793-3041

Physical: 1313 Sherman Street, Room 215, Denver, CO 80203

Mailing: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

chris.girardi@state.co.us | <https://drms.colorado.gov/>



FinalExtensionApproval_CorrectiveActions_KingPit_M1987012.pdf
327K



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

August 29, 2025

Mr. Paul Bottini
Southwest Ready-Mix, Inc.
117 White Pine Dr.
Alamosa, CO 81101

**Re: Approval of Extension Request to Complete Outstanding Corrective Actions
King Pit, Permit No. M-1987-012**

Dear Mr. Bottini:

On September 5, 2024, the Division of Reclamation, Mining and Safety (“Division” or “DRMS”) performed a routine monitoring inspection of the King Pit, M-1987-012. As a result of the inspection, the Division cited problems that require corrective action.

The Operator has requested a 90-day extension to complete the remaining outstanding corrective actions. Given these corrective actions have been requested since the inspection report was issued on November 5, 2024, the Division will provide approval of an extension of 45 days to complete the remaining corrective actions.

Please provide clear photo documentation that earthwork activities have removed erosion gullies in the South Pit Area, and a figure with supporting photo documentation that depicts the current North Pit Area highwall length, which should be no greater than 300 feet. Please complete these corrective actions and provide evidence by **October 13, 2025**. Please note that if the corrective actions are not properly addressed, and evidence provided to the Division by the date provided above, the listed problems could be escalated to the level of possible violation and referred to the Mined Land Reclamation Board for further action.

If you have any questions, please contact me by telephone at (720) 793-3041, or by email at chris.girardi@state.co.us.

Sincerely,

Chris Girardi



Environmental Protection Specialist

cc: Jared Ebert; DRMS
Jodi Schreiber, PFM Consulting LLC