



Tamme Bishop, P.E.
Consulting Engineer

November 24, 2025

Rob Zuber
Division of Reclamation, Mining & Safety
1313 Sherman St., Room 215
Denver, CO 80203

Re: Bowie No. 2 Mine
Permit C-1996-083,
Minor Revision #213,
Adequacy Response #1

Dear Mr. Zuber:

The DRMS transmitted its adequacy response for the Bowie No. 2 Mine via email dated November 18, 2025. On behalf of Bowie Resources, LLC following are its responses to the DRMS's comments and concerns.

1. **DRMS:** It appears that the text in Section 2.03 of the Permit Application Package (PAP) needs to be updated to include "Legacy Ranches" as an owner of record. Also, please check that "Legacy Ranches" is the official name of this company or if "Legacy Ranches LLC" (or similar) is more accurate. As appropriate, Map 01 should also be revised to reflect the official name.

BOW: Please see revised **Map-01**.

2. **DRMS:** It is unclear why Section B-B' has not been updated on Figure 1. Please explain why this is not necessary or revise the figure with a revised section. Also, please explain why there is no section for I-I' when it is shown on the plan view.

BOW: Please see revised **Figure 1**. Section I-I' should not appear on Figure 1, that section is shown on Figure 5. Section B-B' has been revised.

Please let me know if you have any questions.

Sincerely,

Tamme Bishop

Tamme Bishop, P.E.

tammekb@gmail.com