



MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Wattenberg Disturbance Reclamation	MINE/PROSPECTING ID#: M-2022-021	MINERAL: Reclamation only permit	COUNTY: Weld
INSPECTION TYPE: Monitoring	WEATHER: Windy	INSP. DATE: December 9, 2025	INSP. TIME: 10:30
OPERATOR: Holcim - WCR, Inc.	OPERATOR REPRESENTATIVE: Wyatt Webster	TYPE OF OPERATION: 110c - Construction Limited Impact	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: Complete Bond	BOND AMOUNT: \$1,911.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
INSPECTOR(S): Patrick Lennberg	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: December 16, 2025	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>N</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION--- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN--- <u>N</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>Y</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

The Wattenberg Reclamation Only, site, (M2022-051) permit was inspected by Patrick Lennberg with the Division of Reclamation, Mining, and Safety (Division/DRMS). The inspection was completed as part of the Division's routine monitoring program. The site was previously inspected by the Division on February 21, 2023, as part of the Succession of Operators application (SO-1) that transferred the permit from Aggregate Industries to Holcim – WCR, Inc. Wyatt Webster representing the Operator, Holcim – WCR, Inc., was present during the inspection.

The site is in Weld County approximately 2 miles northwest of Brighton, Colorado. The site is accessed from the south via Weld County Road 23 ½ approximately 0.75 miles north of the intersection of WCR 23 ½ and East 168th Ave. The site is located immediately next to the Wattenberg Lakes, M2004-051, permit boundary. The affected lands are owned by Holcim – WCR, Inc. The approved post-mining land use is rangeland. A mine sign was observed at the entrance to the mine as required by Rule 3.1.12.

The site is a 110-construction limited impact operation permitted for 1.5 acres. The permit was issued by the Division on August 25, 2022, as a "reclamation only" permit. The site was not active at the time of the inspection.

The site was recently re-seeded and had straw mulch crimped into place. However, in the northern permit area it appears that an oil and gas well was recently plugged and abandoned. This activity ruined the re-seeding and mulching efforts that were recently completed, and the Operator will have to re-seed the area again.

The Division evaluated the financial warranty and determined the currently held financial warranty amount is sufficient at this time.

Photographs taken during the inspection are attached.

Please contact Patrick Lennberg by email at patrick.lennberg@state.co.us if you have any questions regarding this report.

Inspection Contact Address

Wyatt Webster
Holcim - WCR, Inc.
1687 Cole Blvd., Suite 300
Golden, CO 80401

cc: Jared Ebert, DRMS

ec: Wyatt Webster, Holcim – WCR, Inc., wyatt.webster@amrize.com

PHOTOGRAPHS



Photo 1: Mine sign at the primary mine entrance



Photo 2: Looking north across the permit area from the southern end of the site



Photo 3: Looking south across the permit area from the northern end of the site



Photo 4: Looking south across the permit area from the northern end of the site



Photo 5: The permit area at the north end of the site affected by the oil and gas operation



Photo 6: The oil and gas well



Photo 7: Looking south from the north end of the permit area



Photo 8: Aerial image from 11/2025 showing the site permit boundary and area affected by oil and gas operations