## STATE OF COLORADO

#### **DIVISION OF RECLAMATION, MINING AND SAFETY**

Department of Natural Resources

1313 Sherman St., Room 215 Denver, Colorado 80203 Phone: (303) 866-3567 FAX: (303) 832-8106



April 20, 2012

Gilbert Lee Central Aggregates, Inc. P.O. Box 1877 Rifle, CO 81650 John W. Hickenlooper Governor Mike King Executive Director Loretta E. Piñeda Director

RE: West Rifle Pit, Permit No. M-1981-006, Unresolved Problem(s) Noted in a Past Inspection Report

Dear Mr. Lee:

According to records kept by the Division of Reclamation, Mining and Safety, some problem(s) noted in a past mine site inspection report have not been corrected. If the problem(s) have already been corrected, documentation of the corrective actions taken to correct the problem(s) must be submitted to our office.

Please see the enclosed inspection report for the above noted mine site, issued as a result of a past inspection of this site. Problems noted in this report that remain unresolved according to our records, have been highlighted.

To avoid potential future enforcement actions for non-compliance with State Statutes, Rules and Regulations, and/or conditions specified in your permit for this site, you must submit compliance documentation with the corrective actions specified for <u>each</u> of the indicated problems by *Friday, May 04, 2012*.

If you require additional information, have questions or concerns, please feel free to contact me.

Central Aggregates, Inc.

Page 2 of 3 April 20, 2012

Sincerely,

Dustin Czapla/

**Environmental Protection Specialist** 

Division of Reclamation, Mining and Safety

101 South 3<sup>rd</sup> Street, Room 301

Grand Junction, CO 81501

Ph: 970.243.6299

Enclosed: Certificate of Service

March 8, 2012 Inspection Report (pg. 1)

Cc:

Central Aggregates, Inc. Page 3 of 3 April 20, 2012

## **CERTIFICATE OF SERVICE**

I, Dustin Czapla, hereby certify that on Friday, April 20, 2012 I deposited a true copy of the foregoing *Unresolved Problems letter* in the United States Mail, postage paid, addressed to the following:

Gilbert Lee Central Aggregates, Inc. P.O. Box 1877 Rifle, CO 81650

Dustin Czapla

Division of Reclamation, Mining and Safety

 ${\it Environmental \ Protection \ Specialist}$ 



# COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY MINERALS PROGRAM INSPECTION REPORT

PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:	MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
West Rifle Pit	M-1981-006	Sand and gravel	Garfield
INSPECTION TYPE:	INSPECTOR(S):	INSP. DATE:	INSP. TIME:
Monitoring	Dustin M. Czapla	March 8, 2012	09:00
OPERATOR:	OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:	
Central Aggregates, Inc.	Gilbert Lee	112c - Construction Regular Operation	

REASON FOR INSPECTION:	BOND CALCULATION TYPE:	BOND AMOUNT:	
Normal I&E Program	Complete Bond	\$10,500.00	
DATE OF COMPLAINT:	POST INSP. CONTACTS:	JOINT INSP. AGENCY:	
NA	None	None	
WEATHER:	INSPECTOR'S SIGNATURE:	SIGNATURE DATE:	
Clear	ORIGINAL SIGNED	April 20, 2012	

The following inspection topics were identified as having Problems or Possible Violations. OPERATORS SHOULD READ THE FOLLOWING PAGES CAREFULLY IN ORDER TO ASSURE COMPLIANCE WITH THE TERMS OF THE PERMIT AND APPLICABLE RULES AND REGULATIONS. If a Possible Violation is indicated, you will be notified under separate cover as to when the Mined Land Reclamation Board will consider possible enforcement action.

### 1. INSPECTION TOPIC: Availability Of Records

**PROBLEM/POSSIBLE VIOLATION:** Problem: The Division lacks an adequate map showing the existing site conditions and the affected area of the site. A map, drafted by Jerry Bauer, was submitted to the Division on January 11, 2007 by the Operator. During review of this map it was noted that the map scale (1"=120") appears to be incorrect. Also, the map appears to incorrectly outline the permit boundary for the site. An accurate site map is necessary for the Division to adequately evaluate the reclamation liability for this site.

**CORRECTIVE ACTIONS:** Submit a map of the site which adequately shows the permit area with the acreage labeled, and the current conditions of the site.

### **CORRECTIVE ACTION DUE DATE: 4/16/12**

### 2. **INSPECTION TOPIC:** Financial Warranty

**PROBLEM/POSSIBLE VIOLATION:** Problem: The financial warranty is not adequate to reclaim the site in accordance with the approved reclamation plan. This is a failure to maintain the proper financial warranty amount to complete reclamation of the affected lands pursuant to C.R.S. 34-32.5-117(4)(b) of the Act.

**CORRECTIVE ACTIONS:** The operator shall submit adequate financial warranty, as determined by the Division. The Division will be sending a separate surety increase notice to the operator regarding the increase of the financial warranty. The operator will have 60 days from the date on the surety increase notice to post the additional financial warranty.

**CORRECTIVE ACTION DUE DATE: 5/16/12**