

STATE OF COLORADO

DIVISION OF RECLAMATION, MINING AND SAFETY Department of Natural Resources

1313 Sherman St., Room 215
Denver, Colorado 80203
Phone: (303) 866-3567
FAX: (303) 832-8106



February 26, 2013

Randy Oser
Wildcat Mining Corporation
1630 Ringling Blvd.
Sarasota, FL
34236

John W. Hickenlooper
Governor

Mike King
Executive Director

Loretta Piñeda
Director

RE: May Day Idaho Mine Complex, Permit No. M-1981-185, Technical Revision (TR4), Adequacy Review (3)

Dear Mr. Oser:

On February 26, 2013 the Division of Reclamation, Mining and Safety (Division) received Wildcat Mining Corporations's (WMC) response to *Adequacy Review (2)*. An additional 24" CMP was appropriately proposed in order to convey a 10-year, 24 hour stormwater event beneath the access road. Review of WMC's response determined that the following issue shall be adequately addressed before TR4 can be considered for approval.

1. On Sheet 3 in Appendix B, the toe-wall width was not increased to account for the additional CMP. The width of the toe-wall should be increased in order to prevent undercutting around the pipes during high flows. Please review this figure and revise as necessary. In your response, please include the spacing to be placed between the three CMP's.

If you require additional information, have questions or concerns, please contact me at the DRMS Grand Junction Field Office.

Sincerely,



Dustin Czaplak

Environmental Protection Specialist
Division of Reclamation, Mining and Safety
101 South 3rd, Suite 301
Grand Junction, CO 81501
Phone: (970) 243-6299
Fax: (970) 241-1516

Ec: Mike Thompson
Daniel Madruga