

COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY COAL PROGRAM INSPECTION REPORT



PERMIT INFORMATION

Permit Number: C-1982-056 Mine Name: Foidel Creek Mine Operator: Twentymile Coal, LLC Operator Address: Mr Jerry Nettleton 29515 Routt County Road No. 27 Oak Creek, CO 80467	County: Routt Operation Type: Underground Permit Status: Active Ownership: Federal Operator Representative Present: Brian Watterson		
Operator Representative Signature: (Field Issuance Only)			

INSPECTION INFORMATION

Inspection Start Date: April 9, 20 Inspection Start Time: 09:00 Inspection End Date: April 9, 201 Inspection End Time: 14:00		Inspection Type: Coa Inspection Reason: N Weather: Cloudy	•
Joint Inspection Agency:		Joint Inspection Contacts:	
None			
Post Inspection Agency:		Post Inspection Contacts:	
None			
Inspector(s):	Inspector's Signature: Signature Date:		
Jason D. Musick	0	ham Marsil	4/11/2013
		· <i>U</i>	4/11/2013

Inspection Topic Summary NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable			
N - Air Resource Protection	N - Roads		
N - Availability of Records	N - Reclamation Success		
NA - Backfill & Grading	N - Revegetation		
NA - Excess Spoil and Dev. Waste	N - Subsidence		
N - Explosives	N - Slides and Other Damage		
N - Fish & Wildlife	N - Support Facilities On-site		
R - Hydrologic Balance	N - Signs and Markers		
R - Gen. Compliance With Mine Plan	N - Support Facilities Not On-site		
N - Other	N - Special Categories Of Mining		
N - Processing Waste	N - Topsoil		
	_		

COMMENTS

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18: Ponds T, B, C, D, E, F, G, 6NM sediment pond, the Fish Creek Tipple Pond, the Fish Creek borehole ponds, and the Pit Pond were observed during the inspection. Ponds T, B, D, E, and the Fish Creek Tipple Pond were discharging at the time of the inspection. No problems were noted at the observed ponds with the exception of the following:

- Non-coal waste (old culvert) in the ditch between the emergency and primary spillways of Pond F should be removed.
- The silt fence at the Pond D outlet will require re-established as designed.
- The outlet of the culvert under the train loadout road at Pond C is $\sim 1/2$ full of material and will need cleared.





Pond F Pond E

Number of <u>Partial</u> Inspection this Fiscal Year: 7 Number of Complete Inspections this Fiscal Year: 3



Number of <u>Partial</u> Inspection this Fiscal Year: 7 Number of <u>Complete</u> Inspections this Fiscal Year: 3





Fish Creek Tipple Pond

6 MN Sediment Pond

At the time of the inspection TC was discharging to Fish Creek at Site 115, the Fish Creek Borehole site. The discharge is due to a failed pump, which has forced TC to tie into the water pipe from 18 LT and send the water underground at the Fish Creek Borehole. The construction of the 18 LT pipe is currently bonded under the Foidel Creek Mine Permit.



18 LT Water Pipeline at Fish Creek Borehole

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions are pending and none were taken as a result of this inspection.