

Czapla - DNR, Dustin <dustin.czapla@state.co.us>

Permit M-1977-196 Buena Vista Pit- Response to Inspection

1 message

Denise Gonzales <denise@cpucorp.net>
To: Dustin.Czapla@state.co.us

Tue, Aug 27, 2013 at 10:55 AM

Dustin,

Please find attached photos of the corrective action for the above referenced pit. We have already submitted to increase on the warranty bond. Please let me know if you have any questions or require further information. Thank you

Denise Gonzales

Hard Rock Paving & Redi Mix, Inc.

(719) 275-4555 Office

(719) 275-8897 Fax

(719) 429-9595 Cell

denise@cpucorp.net



RECEIVED

AUG 2 7 2013

GRAND JUNCTION FIELD OFFICE
DIVISION OF
RECLAMATION MINING & SAFETY

From: Brian Sack [mailto:bsack51@yahoo.com]

Sent: Friday, August 23, 2013 4:55 PM

To: Denise Gonzales
Cc: John Paul Ary
Subject: BV Pit

Denise,

Here are the updated BV Pit pictures.

We got tired of waiting on Scott Pelino we just took care of it ourselves.

- -Figure 1 is the far west gully that has been filled, graded and re-seeded.
- -Figure 1-1 is the access road that goes through the north end of the property, we slopped the road to the adjacent slope so flow would continue down the road and not cross it. We also replaced the safety berm bordering the pit and re-seeded it.
- -Figure 2 is the center gully which is fed by a culvert at the top end that crosses underneath the access road; the culvert is not on our property. We decided to keep the drainage and address the flow and sediment control. We placed check dams and a 10' long rip rap flare at the top and bottom of the slope.
- -Figure 2-1 is showing the rip rap flare at the bottom of the slope
- -Figure 3 is the far east gully that is much of the same at figure 2. The water cannot be diverted so we decided to control the flow and sediment in the same fashion as figure 2.
- All disturbed areas have been reseeded

Please let me know if this is sufficient enough.

Brian Sack

General Manager

Hard Rock Paving & Redi-Mix

Office: 719-539-2222

Mobile: 719-221-9073

Fax:719-539-6753

brian@arycorp.com



4 attachments



Figure 1.JPG 4076K



Figure 1-1.JPG 4105K



Figure 2.JPG 4185K



Figure 2-1.JPG 4112K







