



COLORADO

Division of Reclamation,
Mining and Safety

Department of Natural Resources

1313 Sherman Street, Room 215
Denver, CO 80203

September 30, 2014

Mr. John P. Ary
Fremont Paving & Redi-Mix, Inc.
P.O. Box 841
Cañon City, CO 81215

**RE: Florence South Pit, File No. M-2014-045;
Resolved Corrective Actions**

Dear Mr. Ary:

The Division of Reclamation, Mining and Safety (Division) has determined that the Corrective Actions assigned as a result of the May 20, 2014 inspection have been resolved. The following summarizes the problems identified, documentation received and date resolved:

Problem/Possible Violation	Corrective Action Documentation	Resolution Date
New Structures agreement with Centel for the power line running through the permit boundary is required.	New signed agreement with Centel received with TR-02 on July 11, 2014.	July 11, 2014
Collapse in the southern access ramp rising from the pit floor requires repair.	Letter documenting repair received September 16, 2014.	September 16, 2014
Tamarisk (salt cedar) trees present within the permit area.	Weed control plan submitted as TR-02. Approved July 14, 2014.	July 14, 2014

If you have any questions, please contact me (303-866-3567 ext. 8169).

Sincerely,

Timothy A. Cazier, P.E.
Environmental Protection Specialist

ec: Tom Kaldenbach, DRMS
DRMS file

