


# Inspection



QATESTOCR



November 13, 2014

Colorado Division of Reclamation, Mining, and Safety  
Ms. Amy Eschberger  
Environmental Protection Specialist  
1313 Sherman Street, Room 215  
Denver, CO 80203

RECEIVED

410V 13 2014

DIVISION OF RECLAMATION  
MINING AND SAFETY

Re: M-1993-004 Navajo Mine, Elbert County, Colorado  
Corrective Action Extension request

Dear Ms. Eschberger:

General Shale Brick, Inc. (GSB) has received your inspection report dated October 15, 2014 for the Navajo Mine. The inspection requested that GSB stake the affected area boundary.

Upon review of the permit document, it appears that the affected area boundary parallels the permit boundary except where noted in the document. In order for the surveyor to set the affected area boundary, points they will need to locate the permit boundary which is the same as the property boundary. They are having difficulty locating the north line of the permit boundary in the county road.

The same surveyor contracted to work on the Buffalo Mine survey work for the corrective action is working on this project simultaneously. Therefore, the survey work is taking longer than anticipated because of the additional Buffalo Mine survey work.

GSB is requesting an extension of the due date of November 15, 2014. We plan to have the markers set and submit photographic evidence submitted by December 12, 2014; provided that we can drive the posts into the ground because the ground may be frozen.

Please feel free to contact me with any questions at 303-783-3058 or by email at [jason.mcgraw@generalshale.com](mailto:jason.mcgraw@generalshale.com).

Sincerely,  
General Shale Brick, Inc.

Jason E. McGraw P.E.  
Mine Supervisor