

JAN 262015

DIVISION OF RECLAMATION, MINING & SAFETY MINERALS

110c Annual Report

Permittee Name:	Dilleys Sand & Gravel	Permit Number:	M-1981-004
Operation Name:	Ayers Pit	County:	Morgan
Annual Fee Due:	\$323.00	Anniversary Date:	February 2, 2014
Permit Acreage:	9.80	Current Bond Amt:	\$3,120.00

According to C.R.S. 34-32.5-116 or 34-32-116, each year, on the anniversary date of the permit, an operator shall submit the Annual Fee, an Annual Report and Map showing the extent of current disturbances to affected land, required monitoring information, reclamation accomplished to date and during the preceding year, any new disturbance that is anticipated to occur during the upcoming year, any reclamation that will be performed during the upcoming year, the dates for the beginning of active operations, and the date active operations ceased for the year.

Information contained in this report will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.

				•			•								
1.	Is the site identification sign posted in accordance with Rule 3.1.12(1).											YES	0	NO	
2.	. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2).											YES	5	NO	
3.	3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.										lete)?	YES	5	NO	
4.	4. What was the date of last excavation, processing or hauling activity at the mine?														
5.	5. Does the mine operate more than 180 days per year? If "NO", please review Rule 1.13 to assure that your mine is in compliance.											YES	5 ,	NO	
6.	. Has this mine been granted: a) approval of TEMPORARY CESSATION Status? b) approval for INTERMITTENT OPERATION?											YES YES		NO NO	
7.	Number of acre	es currently	affected	(mining +	· incor	nple	te and or unrele	easec	l reclan	nation).					
8.	. Number of acres that were newly affected during the current report year.											None			
9.	Number of acre	es that were	reclaime	d during	he cui	rent	report year.								
10. Estimated new acreage to be affected in the next report year.										Unknown					
11. 12.	Estimated acres Total acres in	s to be recla various stag	imed in t	he next ro lamation,	eport y	ear. perr	nitted mining a	ctivi	ties bes	zan:		nkro	الما	1	
	Total acres backfilled: N/A		Total acr seeded w approved	cs / N/A I mix:			Total acres w/topsoil replaced:	6		Total a		h:	0		
	Total acres graded: fortiliz apvd for			w/Acne			Topsoil replacement depth (in.):	()	Mulch application rate (tons/ac):		ion	0		
	Seed application method:			Fertilize applicat method:	ion	Ċ)		Mulch applic metho	ation	0				

