

John Dewitt

MINING MAP

ENDERSEN PIT

(M-1979-111)

MAP BY: JOHN DEWITT

FEBRUARY 18, 2015

6.3 ACRES

ARICKAREE

RIVER

415 FT

595 FT

HAUL
ROAD

STOCKPILE
AREAS

512 FT

DIRECTION
OF MINING

CLAY STOCKPILE LEFT BY CDOT
FOR LAND OWNER

604 FT

SCALE: 1" = 82.6'

X---X = BARBED WIRE FENCE
O = BOUNDARY MARKERS

39.465255°, -103.263803°

39.464113°, -103.263814°

39.465172°, -103.265906°

39.463768°, -103.265906°

COUNTY HWY 63

John D. Dewitt

RECLAMATION MAP

595 FT

39.465172° -103.265906°

39.465255° -103.263803°

STOCKPILES REMOVED TOPSOIL BENEATH
RESEEDDED WITH NRCS APPROVED MIX.
HAUL ROAD RECLAIMED AND SEEDED.
CLAY STOCKPILES WILL REMAIN UNLESS
REMOVED BY LANDOWNER.



512 FT

CLAY STOCKPILE LEFT BY CDOT
FOR LANDOWNER

604 FT

39.464113° -103.263814°

X---X = BARBED WIRE FENCE
O = BOUNDARY MARKERS

SCALE: 1" = 82.6'

ENDERSEN PIT
(M-1979-111)

MAP BY: JOHN DEWITT
FEBRUARY 18, 2015

6.3 ACRES

ARICKAREE
RIVER
415 FT

Division of Reclamation, Mining, and Safety

Fee Receipt for M1979111

Lincoln County

000000000

Receipt #: 19028

Date: 02/24/2015

Permit: M1979111

Payment Method	Revenue Code	Fee Description/Notes	Amount
012578 msr	4300-MTR0	Minerals Technical Revision M1979-111	\$216.00
Receipt Total:			\$216.00